

- K Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To resurvey damaged part(s) during resurvey
 - Parts price are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurer/Third party

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Acknowledged by Repairer
 Signature:
 Date:

AIG ASIA PACIFIC INSURANCE PTE LTD
 Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 19.10.2020
 VEH NO : SJH1321G
 MODEL : Honda Stepwagon
 D O A : 13.10.2020
 YR REF : SME8786H

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJH1321G (HONDA STEPWAGON)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Side Bumper - LH & RH <i>Repis</i>	2	790.00 X
2	Rear Side Bumper Garnish - LH & RH <i>hol new</i>	2	370.00 X
3	Rear End Panel Outer Garnish <i>deband</i>	1	181.90 ✓
4	Rear End Panel Top Garnish <i>hol new</i>	1	203.40 X
5	Rear Door - LH <i>dented</i>	1	1,850.40 ✓
6	Rear Door Lock - LH <i>hol new</i>	1	248.40 X
7	Rear Door Weatherstripe - LH <i>hol new</i>	1	168.20 X
8	Rear Door Hinge - LH <i>best</i>	1	59.40 ✓
9	Rear Door Outer Cover - LH <i>deband</i>	1	592.40 ✓
10	Rear Door Outer Cover Black Moulding - LH <i>hol new</i>	1	121.40 X
11	Rear Door Outer Chrome Garnish - LH <i>hol new</i>	1	295.40 X
12	Rear Door Glass Moulding - LH <i>new</i>	1	129.60 ✓
13	Rear Door Inner Trim Board - LH <i>deband</i>	1	301.20 ✓
14	Honda Logo <i>new</i>	1	96.50 ✓
15	Stepwagon Wording <i>new</i>	1	78.10 ✓
16	Rear Door - RH <i>dented</i>	1	1,204.40 ✓
17	Rear Door Lock - RH <i>Damaged</i>	1	341.20 ✓
18	Rear Door Weatherstripe - RH <i>hol new</i>	1	180.40 X
19	Rear Door Outer Cover - RH <i>deband</i>	1	380.30 ✓
20	Rear Door Outer Cover Black Moulding - RH <i>hol new</i>	1	121.40 X
21	Rear Door Outer Chrome Garnish - RH <i>hol new</i>	1	158.20 X
22	Rear Door Glass Moulding - RH <i>new</i>	1	129.40 ✓
23	Rear Door Inner Trim Board - RH <i>hol new</i>	1	301.20 X
24	Spada Wording <i>new</i>	1	88.40 ✓

8,391.20
 (1,678.24)
 \$ 6,712.96

Less 20%
 5433.2
 4346.56

RE : ESTIMATE FOR ACCIDENT REPAIR SJH1321G (HONDA STEPWAGON)

S/NETT ITEMS

1	Rear Number Plate <i>hol me</i>	1	\$	30.00	X
2	Rear Number Plate Holder <i>ut</i>	1	\$	30.00	✓
3	Reverse Sensor <i>Dangd</i>	1	\$	280.00	200
4	Rear Door Outer Cover Clips - LH <i>NRC</i>	1 set	\$	30.00	20
5	Rear Door Glass Sealant - LH <i>neu</i>	1	\$	60.00	✓
6	Rear Door Inner Trim Board Clips - LH <i>neu</i>	1 set	\$	30.00	✓
7	Rear Door Outer Cover Clips - RH <i>neu</i>	1 set	\$	30.00	20
8	Rear Door Inner Trim Board Clips - RH <i>hol me</i>	1 set	\$	30.00	X
9	Rear Door Glass Sealant - RH <i>neu</i>	1	\$	60.00	✓
10	Rear Camera <i>hol me</i>	1	\$	480.00	X
				420.	
				<hr/>	
			\$	1,060.00	
				<hr/>	
Total Parts			\$	7,772.96	

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,000.00	700
2	To putty & spray up paint works	\$	1,200.00	600
3	To check wiring	\$	50.00	30
4	To underseal	\$	150.00	50
5	To remove reverse sensor	\$	100.00	50
6	To remove upholstery	\$	100.00	50
7	To remove rear LH & RH door glasses	\$	240.00	120
8	To transfer rear LH & RH door fittings	\$	240.00	160
9	To remove rear camera	\$	100.00	50
				1810
Total Labour			\$	3,180.00
Grand Total			\$	10,952.96

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 6576.56
2/S: 5250
05 Days