



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
 No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
 TELEPHONE: 6748 2795 FAX: 6747 2373
 Registration No.: 203165/00D

MV-6800
 LTA-484
 nett 6316

Not Authorized
 b/m

15/10/20

TOTAL LOSS

LKK

DATE: 19/10/2020 OUR REF: UAPL1427
 REPAIR ESTIMATE TO YOUR ABOVE YAMAHA FJR1300 NO: FX2035P
 NETT ITEM:-

1 FRONT HEADLAMP ASSY	cl a	\$	650.00	✓
1 FRONT HEADLAMP BRACKET	n 1	\$	200.00	X
1 FRONT FEARING ASSY	cl a	\$	800.00	✓
2 FRONT SIDE FEARING (LEFT/RIGHT)	cl a	\$	2,200.00	✓
2 FRONT TOP SIDE FEARING (LEFT/RIGHT)	cl a	\$	720.00	ipc
2 FRONT FORK ASSY	360 o/s cl a	\$	3,000.00	✓
2 FRONT BEARING CONE	cl a	\$	160.00	✓
1 FRONT SPORT RIM	n	\$	380.00	X
1 FRONT RIM SHAFT	n 1	\$	70.00	X
2 FRONT RIM BEARING	n	\$	40.00	X
2 FRONT BRAKE DISC (LEFT/RIGHT)	cl a	\$	960.00	X
1 FRONT HANDLE BAR	cl a	\$	170.00	X
1 FRONT BRAKE LEVER	cl a	\$	90.00	✓
2 FRONT FOOT REST (LEFT/RIGHT)	o/s cl a 45	\$	170.00	ipc
1 FRONT BRAKE PEADLE	cl a	\$	95.00	✓
1 FRONT L/H MIRROR	n 1	\$	120.00	X
1 FRONT R/H MIRROR	cl a	\$	120.00	✓
1 FRONT WIND SCREEN	cl a	\$	260.00	✓
1 FRONT WIND SDREEN MOTOR	cl a	\$	450.00	X
1 FRONT WIND SCREEN BRACKET	cl a	\$	1,500.00	X
1 FRONT SPEED METER ASSY	cl a	\$	950.00	X
1 FRONT INNER COVER	cl a	\$	110.00	✓
1 FRONT FUEL TANK	cl a	\$	1,400.00	✓
1 FRONT RADIATOR ASSY	n 1	\$	490.00	X
1 FRONT RADIATORFAN	n 1	\$	280.00	X
2 FRONT SIGNAL LAMP (LEFT/RIGHT)	o/s cl a 60	\$	160.00	ipc
1 FRONT COILER TANK	n 1	\$	90.00	X
1 FRONT EXHAUST header	cl a	\$	680.00	✓
1 FRONT TOP COWLING	cl a	\$	91.00	✓
1 L/H SIDE COWLING	n 1	\$	125.00	X
1 L/H SIDE COWLING INNER PANEL	n 1	\$	95.00	X
1 CENTRE INNER PANEL	n 1	\$	62.00	X
1 FRONT FOOTREST BRACKET	o/s cl a	\$	96.00	✓
2 FRONT FOOTREST RUBBER	Repair	\$	48.00	X
1 GEAR PEDAL	n 1	\$	42.00	X
1 SIDE STAND ASSY	n 1	\$	85.00	X
1 BRAKE PEDAL	Repair	\$	45.00	X
1 REAR HANDLE	cl a	\$	55.00	✓
2 REAR FOOTREST	o/s cl a 45	\$	90.00	ipc
2 REAR FOOTREST BRACKET	o/s cl a 110	\$	220.00	ipc
2 REAR CENTRE SIDE COVER (LEFT/RIGHT)	n 1	\$	240.00	X
1 REAR COVER	n 1	\$	220.00	X
2 REAR SIDE BOX ASSY (LEFT/RIGHT)	cl a 1000 x 2 = 2000	\$	2,800.00	✓
2 REAR EXHAUST PIPE (LEFT/RIGHT)	o/s cl a 1500	\$	4,000.00	ipc
		\$	25,049.00	
		\$	2,504.90	
		\$	22,544.10	

LESS 10%.....

13927



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT
 No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
 TELEPHONE: 6748 2795 FAX: 6747 2373
 Registration No.: 203185/00D

SPECIAL NETT:-

2 FORK OIL	11	\$	30.00	X
1 HANDLE BAR GRIP (1 SET)	1011	\$	90.00	X
1 COOLANT	11	\$	18.00	X
1 ERP COVER	11	\$	20.00	X

LABOUR CHARGES:-

TO TOW VEHICLE TO WORKSHOP	\$	80.00	35
TO RESPARTY DAMAGED PORTION	\$	200.00	✓
TO DISM/RENEW PARTS ANI	\$	1,000.00	380
TO CHECK & REPAIR AND STRAIGHTEN BODY FRAME TO ORIGINAL POSITION	\$	600.00	300
	<u>\$</u>	<u>24,582.10</u>	

24,204.10#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

135.39.3