

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Total Loss

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Oct 2020 <a href="#">Edit Reg</a>		14 Oct 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$13,539.30</b> <a href="#">Edit Estimates</a>	<b>S\$13,539.30</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

[Created by adjuster]

Insured:	<b>MOTALIF BIN MOHAMED</b> , ID: S1665815D, Tel: +6591170174		
Main Claimant:	<b>MOHAMED FADELI BIN SAPI'EH</b> , ID: S8026421F		
Vehicle Reg. No.:	<b>FX2035P</b>	Date of Loss:	10/10/2020 00:00 - :59 [204 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 6666591219SG</b>	Policy/Cover Note No.:	1900161944 (Comprehensive) Coverage: 12/09/2020 - 11/09/2021
Vehicle Reg. No. (Insured):	<b>SMP1505R</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Unimotor Co (HQ)</b> NO 1 KAKI BUKIT AVE 6 #01-94, 417883 Kaki Bukit - Tel: 67182795		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] <a href="mailto:Chee-Heng.Loh@aig.com">Chee-Heng.Loh@aig.com</a>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 26/10/2020]		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

- AIG\_SG (16/10/2020): [Request to upload TP GIA Report](#)

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*FX2035P (6666591219SG)  
[SMP1505R]  
TP  
MOHAMED FADELI BIN SAPI'EH  
Oct 10 2020 12:00AM  
[MOTALIF BIN MOHAMED]  
Unimotor Co

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View			
										View in Browser ▼			
Photos/Images										3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print				
1	15/10/20 16:12	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>			
2	15/10/20 16:12	Chassis Number							Load JPG	<input checked="" type="checkbox"/>			
3	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
4	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
5	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
6	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
7	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
8	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
9	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
10	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
11	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
12	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
13	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
14	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
15	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
16	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
17	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
18	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
19	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
20	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
21	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
22	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
23	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
24	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
25	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
26	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
27	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
28	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
29	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
30	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
31	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
32	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
33	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
34	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			
35	15/10/20 16:15	General View							Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
67	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
68	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
69	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
70	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
71	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
72	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
73	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
74	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
75	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
76	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
77	15/10/20 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
78	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	16/10/20 15:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
84	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	16/10/20 15:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	15/10/20 11:50	EMAIL FROM AIG TO CONDUCT SURVEY	 Load PDF	
2	21/10/20 16:49	GIA REPORT _ FX 2035P.pdf	 Load PDF	
3	04/11/20 10:12	LETTER	 Load PDF	
4	04/11/20 10:12	LTA REBATE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	16/10/20 17:02	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG20011176/USD3S2**Date:** 04/11/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900161944
<b>Claimant Vehicle No :</b>	FX2035P	<b>Insured Vehicle No :</b>	SMP1505R
Date of Loss:	10/10/2020	Nature of Claim:	TP
		Claim No:	6666591219SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FX2035P</b>	Engine No:	P507E007971
Make & Model:	YAMAHA FJR1300, 1.3	Chassis No:	JYARP085000005129
Reg. Date:	23/09/2003 (Man. Year: 2003)	Odometer:	204415 km
Colour:	Silver		
Engine Capacity:	1298 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70ZR17	Rear Tyre Size:	180/50ZR17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,324.10	12,624.30	9,699.80	43.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	915.00	965.00	51.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>24,204.10</b>	<b>13,539.30</b>	<b>10,664.80</b>	<b>44.06</b>

INSPECTION

Date of Assignment:	14/10/2020	Inspected At:	Unimotor Co (HQ) NO 1 KAKI BUKIT AVE 6 #01-94 Singapore 417883
Date Inspected:	15/10/2020		
Estimated Period of Repair:	0.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

The total amount incurred will be Market Value \$ 6,800.00 minus Total Rebate \$ 484.00 =  
\$ 6,316.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP ASSY	Cracked	650.00 FN	*650.00 FN
2	1		*FRONT HEADLAMP BRACKET	Not Necessary	200.00 FN	*- FN
3	1		*FRONT FAIRING ASSY	Cracked	800.00 FN	*800.00 FN
4	2		*FRONT SIDE FAIRING (LEFT / RIGHT)	Cracked	2,200.00 FN	*2,200.00 FN
5	1		*FRONT TOP SIDE FAIRING (LEFT / RIGHT)	O/s Cracked	720.00 FN	*360.00 FN
6	2		*FRONT FORK ASSY	Bent / Twisted	3,000.00 FN	*3,000.00 FN
7	1		*FRONT BEARING CONE	Necessary	160.00 FN	*160.00 FN
8	1		*FRONT SPORT RIM	Repair	380.00 FN	*- FN
9	1		*FRONT RIM SHAFT	Not Necessary	70.00 FN	*- FN
10	2		*FRONT RIM BEARING	Not Necessary	40.00 FN	*- FN
11	2		*FRONT BRAKE DISC (LEFT / RIGHT)	Serviceable	960.00 FN	*- FN
12	1		*FRONT HANDLE BAR	Serviceable	170.00 FN	*- FN
13	1		*FRONT BRAKE LEVER	Scratched	90.00 FN	*90.00 FN
14	1		*FRONT FOOT REST (LEFT / RIGHT)	O/s Broken	170.00 FN	*45.00 FN
15	1		*FRONT BRAKE PEDAL	Cut	95.00 FN	*95.00 FN
16	1		*FRONT L/H MIRROR	Not Necessary	120.00 FN	*- FN
17	1		*FRONT R/H MIRROR	Broken	120.00 FN	*120.00 FN
18	1		*FRONT WINDSCREEN	Broken	260.00 FN	*260.00 FN
19	1		*FRONT WINDSCREEN MOTOR	Serviceable	450.00 FN	*- FN
20	1		*FRONT WINDSCREEN BRACKET	Serviceable	1,500.00 FN	*- FN
21	1		*FRONT SPEED METER ASSY	Serviceable	950.00 FN	*- FN
22	1		*FRONT INNER COVER	Cracked	110.00 FN	*110.00 FN
23	1		*FRONT FUEL TANK	Distorted	1,400.00 FN	*1,400.00 FN
24	1		*FRONT RADIATOR ASSY	Not Necessary	490.00 FN	*- FN
25	1		*FRONT RADIATOR FAN	Not Necessary	280.00 FN	*- FN
26	1		*FRONT SIGNAL LAMP (LEFT / RIGHT)	O/s Cracked	160.00 FN	*60.00 FN
27	1		*FRONT COILER TANK	Not Necessary	90.00 FN	*- FN
28	1		*FRONT EXHAUST HEADER	Dented	680.00 FN	*680.00 FN
29	1		*FRONT TOP COWLING	Cracked	91.00 FN	*91.00 FN
30	1		*L/H SIDE COWLING	Not Necessary	125.00 FN	*- FN
31	1		*L/H SIDE COWLING INNER PANEL	Not Necessary	95.00 FN	*- FN
32	1		*CENTRE INNER PANEL	Not Necessary	62.00 FN	*- FN
33	1		*FRONT FOOTREST BRACKET O/S	Cracked	96.00 FN	*96.00 FN
34	2		*FRONT FOOTREST RUBBER	Repeated	48.00 FN	*- FN
35	1		*GEAR PEDAL	Not Necessary	42.00 FN	*- FN
36	1		*SIDE STAND ASSY	Not Necessary	85.00 FN	*- FN
37	1		*BRAKE PEDAL	Repeated	45.00 FN	*- FN
38	1		*REAR HANDLE	Cut	55.00 FN	*55.00 FN
39	1		*REAR FOOTREST	O/s Broken	90.00 FN	*45.00 FN
40	1		*REAR FOOTREST BRACKET	O/s Cracked	220.00 FN	*110.00 FN
41	1		*REAR CENTRE SIDE COVER (LEFT / RIGHT)	Not Necessary	240.00 FN	*- FN
42	1		*REAR COVER	Not Necessary	220.00 FN	*- FN
43	2		*REAR SIDE BOX ASSY (LEFT / RIGHT)	Cracked	2,800.00 FN	*2,000.00 FN
44	1		*REAR EXHAUST PIPE (LEFT / RIGHT)	O/s Dented	4,000.00 FN	*1,500.00 FN
45	2		*FORK OIL	Not Necessary	30.00 FS	*- FS
46	1		*SET HANDLE BAR GRIP	Torn	90.00 FS	*90.00 FS
47	1		*COOLANT	Not Necessary	18.00 FS	*- FS
48	1		*ERP COVER	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

**Sub Total (\$)**      **24,787.00**      **14,017.00**  
**- Nett Item Discount on N Items 10.00/10.00% (\$)**      2,462.90      1,392.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (\$)</b>	<b>22,324.10</b>	<b>12,624.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW VEHICLE TO WORKSHOP.	New	80.00	35.00
2	TO RESPRAY DAMAGED PORTION.	New	200.00	200.00
3	TO DISM/RENEW PARTS ANI.	New	1,000.00	380.00
4	TO CHECK & REPAIR AND STRAIGHTEN BODY FRAME TO ORIGINAL POSITION.	New	600.00	300.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,880.00</b>
				<b>915.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >