

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

T.P.M.S.L.G

Tronme

15 October 2020

QUOTATION FOR ACCIDENT REPAIR OF SGP4967S TOYOTOA VIOS

THIRD PARTY INSURER: MSIG INSURACNE

S/No.	Parts List	Qty	Amount (\$)
1.	Front fender RH <i>Dented</i>	1	\$ 420.60 ✓
2.	Front fender inner shield RH <i>Dented</i>	1	\$ 125.10 ✓
3.	Front door RH <i>Dented</i>	1	\$ 709.90 ✓
4.	Front door outer protector RH <i>Dented</i>	1	\$ 72.50 ✓
5.	Front door window glass outer moulding RH <i>New</i>	1	\$ 137.30 +
6.	Front door outer handle RH <i>New</i>	1	\$ 132.10 +
7.	Front door black tape RH <i>New</i>	2	68.00 \$ 136.00 +
8.	Front door hinge U/L (RH) <i>New</i>	2	64.60 \$ 129.20 +
9.	Front checker RH <i>New</i>	1	\$ 156.80 +
10.	Front door weather strip RH <i>New</i>	1	\$ 120.60 +
11.	Front door mechanism lock RH <i>Dented</i>	1	\$ 281.90 ✓
12.	Front door lock striker RH <i>New</i>	1	\$ 55.00 +
13.	Front door window glass regulator RH <i>Byd</i>	1	\$ 216.60 ✓
14.	Front door window glass regulator motor RH <i>New</i>	1	\$ 393.30 +
15.	Front door inner trim board RH <i>New</i>	1	\$ 587.10 +
16.	Front door inner trim board clip RH <i>New</i>	10	4.50 \$ 45.00 +
17.	Front door speaker RH <i>New</i>	1	\$ 168.60 +
18.	Rear door RH <i>Dented</i>	1	\$ 872.50 ✓
19.	Rear door outer protector RH <i>Dented</i>	1	\$ 72.50 ✓
20.	Rear door window glass outer moulding RH <i>New</i>	1	\$ 137.30 +
21.	Rear door outer handle RH <i>New</i>	1	\$ 132.10 +
22.	Rear door black tape RH <i>New</i>	2	68.00 \$ 136.00 +
23.	Rear door weather strip RH <i>New</i>	1	\$ 156.80 +
24.	Rear door hinge U/L (RH) <i>New</i>	2	64.60 \$ 120.60 +
25.	Rear door checker RH <i>New</i>	1	\$ 68.50 +
26.	Rear door mechanism lock RH <i>New</i>	1	\$ 281.90 +
27.	Rear door lock striker RH <i>New</i>	1	\$ 55.00 +
28.	Rear door window glass regulator RH <i>Byd</i>	1	\$ 235.60 ✓
29.	Rear door window glass regulator motor RH <i>New</i>	1	\$ 401.20 +
30.	Rear door inner trim RH <i>New</i>	1	\$ 587.10 +
31.	Rear door inner trim board clip RH <i>New</i>	10	4.50 \$ 45.00 +
32.	Rear fender RH <i>Byd</i>	1	\$ 936.60 +
Subtotal before discount			\$ 8125.50
Discount 25%			\$ 2031.37
Subtotal 1			\$ 6094.12

3007.20

2255.40

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

15 October 2020

QUOTATION FOR ACCIDENT REPAIR OF SGP4967S TOYOTOA VIOS

THIRD PARTY INSURER: MSIG INSURANCE

Labour

To check wirings.	\$ 80	30
To remove and reinstall front and rear interior trims, garnishes, seats etc. for necessary repair	\$ 200	X
To transfer front RH door component parts to new door	\$ 160	80
To transfer rear RH door component parts to new door	\$ 160	80
To apply anti-rust undercoat	\$ 80	60
To straighten, repair, realign on affected area and replace damaged parts	\$ 1200	800
To spray painting on affected area	\$ 1200	1000
Total Labour Cost	\$ 3080	

Total Cost Of Repairs(Total cost of parts + Total labour cost) **\$ 9174.12**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adin S
L/S 15/10/20.
05 Days.

total: 430540

L/S: 3K
(Nett Value)