

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8445L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	I40VC PANEL ASSY-RR DR RH	TO REPAIR SEE LABOUR	2,201.10	-
	LESS 20% DISCOUNT		-440.22	-
			1,760.88	-
	<u>NETT ITEMS</u>			
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-8.00	-8.00
			72.00	72.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			200.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.(REPAIR RR FENDER RH).INCLUSIVE OF THE REPAIR OF I40VC PANEL ASSY-RR DR RH.		500.00	280.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	REMOVE/REFIX DOOR PARTS TO ASSIST REP.	NOT NECESSARY	120.00	-
			1,070.00	680.00
	GRAND TOTAL		3,102.88	952.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			952.00

Report Ref No. NS/INC20011182/Esd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.