

COMFORTDELGRO ENGINEERING

Our Job Ref No 305428038

Date : 24.10.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr STEVE

Vehicle Reg No. SHC8445L CTPL 14.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLT4837D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$72.00
 - (b) Labour Charges \$880.00
 - Total for Part-By-Part Repair Cost** \$952.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Steve

Date : 26/10/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428038
REGN NO : SHC8445L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.12.2015
DATE/TIME IN : 14.10.2020 16:10
ACCIDENT DATE : 14.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	I40VC PANEL ASSY-RR DR RH	1 L	2,201.10	20.00	1,760.88	X R
0002 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	/ APC
SUB-TOTAL :						1,832.88

JOB NATURE

0000 20-05	REAR DOOR ADVERTISMENT LOGO RH	100.00	/ APC
0001 20-05	REAR FENDER ADVERTISMENT LOGO RH	100.00	/ APC
0002 L	PANEL BEATING (repair rr fender Rh)	500.00	280
0003 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400
0004 20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP	120.00	X
SUB-TOTAL : 1,270.00			
TOTAL : 3,102.88			

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

AUTHORISED : YES / NO

Steve (LKK) ML
15/10/20, 11:00 am
2 dys
LIS (no part is part by RL)
My ML My

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.10.2020

Time: 16:46:47

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428038
REGN NO : SHC8445L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.12.2015
DATE/TIME IN : 14.10.2020 16:10
ACCIDENT DATE : 14.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-9999-2023-A APP LOGO REAR DOOR L/R CT 1 N 80.00 10.00 72.00

SUB-TOTAL : 72.00

JOB NATURE

0000 20-05 REAR FENDER ADVERTISMENT LOGO RH 100.00

0001 20-05 REAR FENDER ADVERTISMENT LOGO LH 100.00

0002 L PANEL BEATING (repair rr fender Rh) 280.00

0003 23-502 SPRAYPAINT ON AFFECTED AREA 400.00

SUB-TOTAL : 880.00

TOTAL : 952.00

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :