



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20011185/EUf3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 20-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 8654Y	Veh. Inspected	SKT 4510H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003016/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	15/10/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHRU1830FP000134	Colour	GREY
Odometer	92222	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65 R16	FIRESTONE	4 mm
L/H Front Tyre	215/65 R16	FIRESTONE	4 mm
R/H Rear Tyre	215/65 R16	FIRESTONE	4 mm
L/H Rear Tyre	215/65 R16	FIRESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/10/2020	Inspection Date	15/10/2020
Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------