

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SKT4510H

Model: HONDA HRV 1.5 LX CVT
(9/6/2015)

Accident Date : 15/10/20

Location : PIE TOWARDS TUAS BEFORE CLEMENTI EXIT

3P: SLD8654Y (SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	2 pcs	o/s & n/s headlamp bracket lower / BR	143.60	/	-
2	1 pc	Condenser / DD	867.00	688	-
3	1 pc	Radiator X NM	970.00	X	-
4	1 pc	Horn X NM	167.50	X	-
5	1 pc	Front support panel X Repair	780.00	X	-
6	1 pc	o/s headlamp / BR	638.30	/	-
7	1 pc	Front n/s wheel guard X NM	354.60	X	-
	1 pc	Front n/s stone guard (wheel guard) X NM	102.30	X	-
8	1 pc	Front o/s wheel arch garnish / BR	110.00	/	-
9	1 pc	Rear n/s mudflap / TN	365.80	209	-
10	1 pc	Rear n/s air vent / BR	98.00	/	-
11	1 pc	Rear n/s chassis frame outer X R	210.00	X	-
12	1 pc	Rear end panel lock garnish X NM	75.60	X	-
13	1 pc	Rear n/s floor panel (Outer) X R	145.6	X	-
14	1 pc	Rear n/s floor panel (Inner) / DD	98.60	/	-
15	1 pc	Coolent X NM	-	60.00	X
		Sub-Total	5,126.90	60.00	0.00
			20%	0%	0%
		After Less %:	4,101.52	60.00	0.00
		<u>Labour</u>			
1		To remove and refit front radiator	80.00	59	-
2		To remove refit & top-up gas for condensor	150.00	122	-
		Sub-Total	230.00		
		Total:	4,391.52		
		After Less 20%:	3,513.22		

List Price - 1985.50 Labor - 179
- 20%
1588.40

= 1758.40

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

