



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0772/2020/NS
DATE : 14-Oct-20
WIP : 53129

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LOH HIN SIONG
ADDRESS	:	63 CHOA CHU KANG LOOP #01-03 SINGAPORE 689669
TELEPHONE	:	HP +65 91440510
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	180024615-02
VEHICLE NO	:	SLW 9498 A
MODEL CODE	:	AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR	:	9/3/2018
ENGINE NO	:	CVK 050932
CHASSIS NO	:	WAUZZZF58JA050268
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	13-Oct-20
PLACE OF ACCIDENT	:	SIXTH AVE OUTSIDE COLD STORAGE



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 9498 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
1			
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	✓
	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHA HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00 1000	✓
3			
4	✓ TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00 1000	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,972.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9498 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER <i>Detached</i>	\$	2,251.00 ✓	✓ 1800.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	402.00 ✕	
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$	70.00 ✕	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	194.00 ✕	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	225.00 ✕	
6	FRONT BUMPER SPOILER <i>new</i>	\$	529.00 ✕	
7	RADIATOR GRILLE <i>could</i>	\$	2,300.00 ✓	✓ 1840
8	ULTRASOUND SENSOR SUPPORT - LH / RH <i>new</i>	2 \$	102.00 ✕	
9	RADIATOR GRILLE COVER - UPPER <i>new</i> ✕ <i>nn</i>	\$	187.00 ?	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	936.00 ✕	
11	FRONT BUMPER CARRIER <i>new</i> ✕ <i>nn</i>	\$	795.00 ?	
12	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$	123.00 ✓	✓ 98.40
13	FRONT BUMPER TOP COVER <i>could</i>	\$	126.00 ✓	✓ 100.40
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	72.00 ✕	
15	CAUTION SIGN STICKER <i>new</i>	NEC \$	14.00 ✓	✓ 10.80
16	AIRCON STICKER	NEC \$	8.00 ✓	✓ 5.68
17	LOCK CARRIER BRACKET <i>could</i>	\$	136.00 ✓	✓ 108.40
18	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>new</i> ✕ <i>2 nn</i>	\$	56.00 ?	
19	HORN - LH HIGH TONE <i>new</i>	\$	124.00 ✕	
20	SPRING SHACKLE - LH <i>new</i>	\$	29.00 ✕	
SUB TOTAL SPARE PARTS			\$	8,679.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9498 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER <i>3 new</i>		\$ 242.00	+
22	FRONT PARKING AID SEAL RING	4	\$ 14.00	+
23	BONNET <i>Dented</i>		\$ 2,817.00	✓ <i>2253.60</i>
24	BONNET ATTACHMENT PARTS <i>new</i>		\$ 121.00	+
25	BONNET LID HONGE - LH / RH <i>new</i>	2	\$ 830.00	+
26	BONNET IMPACT PROTECTION - CENTRE <i>3</i>		\$ 27.00	✓ <i>21.52</i>
27	BONNET IMPACT PROTECTION - LH <i>3 new</i>		\$ 28.00	✓ <i>21.84</i>
28	BONNET IMPACT PROTECTION - RH		\$ 27.00	✓ <i>21.52</i>
29	BONNET SOUND ABSORBER <i>new</i>		\$ 339.00	+
30	BONNET BOWDEN CABLE - CENTRE <i>3 new</i>		\$ 57.00	+
31	BONNET BOWDEN CABLE - LOWER		\$ 57.00	+
32	BONNET STRIKER - LH / RH <i>3 new</i>	2	\$ 100.00	+
33	BONNET LID LOCK	2	\$ 423.00	+
34	LED HEADLIGHT - LH <i>cancelled</i>		\$ 7,812.00	✓ <i>6249.60</i>
35	LIFT CYLINDER - LH	?	\$ 196.00	?
36	LIFT CYLINDER CORRUGATED PIPE <i>new</i>		\$ 85.00	+
37	RADIATOR AIR GUIDE - LH / RH INNER <i>nn</i>	2	\$ 62.00	?
38	RADIATOR AIR GUIDE - LH / RH OUTER <i>nn</i>	2	\$ 32.00	?
39	RADIATOR AIR GUIDE - UPPER <i>cracked</i>		\$ 16.00	✓ <i>12.72</i>
40	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ <i>60</i>
41	SUNDRIES <i>? nec</i>		\$ 250.00	?
TOTAL SPARE PARTS				:
TOTAL LABOUR CHARGES				:
GRAND TOTAL				:

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:
REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian
: 15/10/20
:
:
:
: Not Authorised, 04 days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT