

Our Job Ref No : 305428039

Date : 17. Oct. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : STEVE

Vehicle Reg No. : SHA1456L

Date of Accident: 14. Oct. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SMS9249L

2. The finalized amount shall be:

(a) Spare Parts after List discount \$981.12

(b) Labour Charges \$580.00

Total for Part-By-Part Repair Cost \$1,561.12

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature :  17/10/2020

Name : Loke Wei Yieng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Steve

Date : 19/10/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.10.2020

REPAIR ESTIMATE

Time: 09:40:15

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305428039
 REGN NO : SHA1456L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 17.07.2019
 DATE/TIME IN : 15.10.2020 09:05
 ACCIDENT DATE : 14.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	180.00	2.00-	180.00
0005 FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	0.20	55.00

SUB-TOTAL : 981.12

JOB NATURE

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAY PAINTING	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 17-01	CHECK ALL LIGHTING	30.00

SUB-TOTAL : 580.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305428039
REGN NO : SHA1456L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 17.07.2019
DATE/TIME IN : 15.10.2020 09:0
ACCIDENT DATE : 14.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,561.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :