

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MOK CHIK KANG

9 RHU CROSS #12-07

SINGAPORE 437436

Contact : 93841064

TP Chim.
Denise.

ESTIMATE

Repair Code : CLM16487

Date in : 13/10/2020

Vehicle Num. : SJG3191G

Model : HONDA CITY 1.5 SV CVT

Chassis/Eng# : MRHGM6660KT000119/L15Z16200239

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
R BUMPER LOWER CENTER GARNISH <i>could</i>	1	59.20	✓ 59.20
REAR BOOTLID <i>Dislaid</i>	1	655.40	565 655.40
REAR BOOTLID 'CITY' EMBLEM <i>2</i>	1	22.00	✓ 22.00
REAR BOOTLID 'I-VTEC' EMBLEM <i>1</i>	1	22.00	✓ 22.00
REAR BOOTLID 'LOGO' EMBLEM <i>1</i>	1	20.00	✓ 20.00
REAR BOOTLID HINGES L/R <i>Best</i>	2	68.40	✓ 136.80
REAR BOOTLID INNER RUBBER GUIDE STOPPER (LONG) L/R <i>new</i>	2	12.50	+ 25.00
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	10.50	+ 21.00
REAR BOOTLID INNER TRIM <i>Not a</i>	1	85.00	+ 85.00
REAR BOOTLID LOCK STRIKER <i>new</i>	1	22.50	+ 22.50
REAR BOOTLID MECHANISM LOCK <i>Doyle</i>	1	90.30	✓ 90.30
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	38.50	+ 77.00
REAR BOOTLID OUTER CHROME HANDLE <i>could</i>	1	148.50	✓ 148.50
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R <i>new</i>	2	18.50	- 37.00
REAR BOOTLID REFLECTOR L/R <i>could</i>	2	205.00	✓ 410.00
REAR BOOTLID WEATHER STRIP <i>at</i>	1	91.60	✓ 91.60
REAR BUMPER <i>Dislaid</i>	1	472.70	✓ 472.70
REAR BUMPER REFLECTOR GARNISH L/R <i>could</i>	2	42.90	✓ 85.80

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MOK CHIK KANG
 9 RHU CROSS #12-07
 SINGAPORE 437436

Contact : 93841064

ESTIMATE

Repair Code : CLM16487

Date in : 13/10/2020

Vehicle Num. : SJG3191G

Model : HONDA CITY 1.5 SV CVT

Chassis/Eng# : MRHGM6660KT000119/L15Z16200239

REAR BUMPER REFLECTOR L/R	<i>2H1 culd, R11 Xlen</i>	2	30.00	<i>20.</i>	60.00
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	25.30		50.60
REAR END PANEL	<i>Deled</i>	1	452.60	<i>365</i>	452.60
REAR END PANEL ANTENNA SENSOR	<i>culd</i>	1	85.00		85.00
REAR END PANEL INNER TOP GARNISH	<i>Deled</i>	1	86.40		86.40
REAR FENDER INNER TRIM BOARD L/R	<i>Xlen</i>	2	228.90	<i>+</i>	457.80
REAR FLOOR PANEL TOP BOARD COVER	<i>form</i>	1	254.30	<i>3669.50</i>	254.30
REAR LH TAILLAMP INNER PANEL	<i>HH Deled Deled</i>	1	89.70	<i>2935.60</i>	89.70
REAR TAILLAMP INNER BLACK GASKET L/R	<i>new</i>	2	18.50		37.00
REAR TAILLAMP L/R	<i>2H1 culd, R11 cul</i>	2	340.70	<i>510.60</i>	681.40
Subtotal before discount					4,736.60
Percentage discount 20%					947.32
Sub-total 1					3,789.28
REAR BOOTLID CAMERA	<i>Deled</i>	1	800.00	<i>400</i>	800.00
REAR BOOTLID INNER TRIM CLIPS - SET	<i>new</i>	1	50.00	<i>+</i>	50.00
REAR BOOTLID NUMBER PLATE	<i>3ent</i>	1	25.00		25.00
REAR BOOTLID NUMBER PLATE HOLDER	<i>new</i>	1	50.00	<i>+</i>	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	<i>new</i>	1	40.00	<i>10</i>	40.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MOK CHIK KANG
9 RHU CROSS #12-07
SINGAPORE 437436

Contact : 93841064

ESTIMATE

Repair Code : CLM16487

Date in : 13/10/2020

Vehicle Num. : SJG3191G

Model : HONDA CITY 1.5 SV CVT

Chassis/Eng# : MRHGM6660KT000119/L15Z16200239

REAR BOOTLID TOP SPOILER	<i>Amber</i>	1	980.00	<i>SW</i>	980.00
REAR BUMPER CLIPS - SET	<i>m</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR - SET	<i>Dangd.</i>	1	380.00	<i>2w</i>	380.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>mm</i>	1	40.00	<i>20</i>	40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>mm</i>	2	50.00	<i>+</i>	100.00
REAR FLOOR PANEL INSULATOR MAT	<i>mm</i>	1	300.00	<i>+</i>	300.00
REAR TAILLAMP CLIPS L/R - SET	<i>mm</i>	2	25.00	<i>✓</i>	50.00
Subtotal before discount					2,895.00
Percentage discount 0%					0.00
Sub-total 2					2,895.00
Parts-total					6,684.28

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

80 100.00
60 140.00
1000 1,300.00
2180 900.00 1,100.00
60 120.00
✓ 80.00

Labour Total

2,840.00

Parts & Labour Total

9,524.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be repaired and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer generated document which requires no signature.
page 3

Adrian Lj
15/10/20
total: 6450.60 OT Dp.
L/S: S-IK ✓