



萬 春 摩 哆

# BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

15/10/2020

MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. XE 4515 U

MODEL: MAN TGS 32.360

DATE OF ACCIDENT: 14/10/2020

YOUR INSURED VEHICLE NO. SHA 312 A

1 pc Rear bumper *bt* ✓  
1 pc Rear number plate *bt* ✓  
1 pc 60km/hr sticker *ne* ✓  
1 pc DANGER HIGHLY FLAMMABLE sticker *ne* ✓

\$ ~~850.00~~ SN ~~400~~  
30.00 SN ✓  
20.00 SN ~~10~~  
180.00 SN ~~100~~ } 540  
\$ 1,080.00

## LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

~~400.00~~ 300 } 700  
~~400.00~~ 700  
\$ 1,880.00

Yours faithfully,

*Redindo*

*Ratna*  
Hp 90010068

3 days

~~4~~ 4/s

19/10/2020

Reg after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: