



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A
GST Regn No. 35191500A

15/10/2020

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. XE 4515 U
MODEL: MAN TGS 32.360
DATE OF ACCIDENT: 14/10/2020
YOUR INSURED VEHICLE NO. SHA 312 A

1 pc	Rear bumper <i>bt</i> ✓	\$	850.00 SN <i>400</i>
1 pc	Rear number plate <i>st</i> ✓		30.00 SN ✓
1 pc	60km/hr sticker <i>re</i> ✓		20.00 SN <i>10</i>
1 pc	DANGER HIGHLY FLAMMABLE sticker <i>re</i> ✓		180.00 SN <i>100</i>
		\$	<u>1,080.00</u>

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.
To changing of the above parts.
To putty and spray painting on accident damaged parts.

	400.00 <i>300</i>
	400.00 ✓
\$	<u>1,880.00</u>

Yours faithfully,

Perdindo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rane
Hp 900 10068

3 days

4/5

19/10/2020

Reg after repair