

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

CC6/11/2001-206/493

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMP 6142X

at Workshop m/s

Choo motor

of

GW 5640R

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£80k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1732

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMP6142X

Yr Regn:

19 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

4/

Make:

Honda Shuttle

C.C

1496

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

19745

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK8 2100162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/10/20

D.O.I.

15/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 6 34059 None h.a

30/10/20 2/5 6000 confirmed with Alan

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) ___ \$ + RS ___ \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

CHOO MOTOR SPRAY PAINTER

1 KAKI BUKIT AVE 6 #01-39 AUTOBAY SPORE 417883

not Authorized
near
2/s \$6000
5 days

VEHICLE No: SMP 6142X

1PC	REAR WINDSCREEN MOULDING	166.30	ner	\$186.40	—
1PC	TAILGATE	1250.20	Bodlyrd	\$1,866.20	—
1PC	TAILGATE 'H' LOGO		ner	\$48.50	✓
1PC	TAILGATE 'SHUTTLE' EMBLEM		ner	\$68.30	✓
1PC	TAILGATE OUTER HANDLE	415.20	cna	\$465	—
2PCS	TAILGATE REFLECTORS @\$650.20	535.50	n/s cro	\$1,300.40	1PC
1PC	TAILGATE INNER LOCK	199.20	twi	\$299.50	—
1PC	TAILGATE INNER TRIM BOARD		de/cro	\$465.30	✓
1SET	TAILGATE INNER TRIM BOARD CLIPS		ner	\$50.00	✓
1PC	TAILGATE WEATHERSTRIP	166.80	twi	\$288.70	—
1PC	REAR BUMPER	1150.60	dis	\$1,420.30	—
2PCS	REAR BUMPER SPONGES @\$195.00		11	\$390.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00		11	\$130.00	X
2PCS	REAR BUMPER REFLECTORS @68.00		n/s cna	\$136.00	1PC
1SET	REAR BUMPER CLIPS	40	ner	\$50.00	✓
1PC	REAR BUMPER TOP CHROME MOULDING		cna	\$233.50	—
1PC	REAR END PANEL	699.20 849.40	3-dyrd	\$899.20	—
1PC	REAR END PANRL TOP GARNISH		11	\$366.50	X
2PCS	TAILLAMPS @\$850.00	625.30	n/s cna	\$1,700.00	1PC
1PC	REAR FLOOR PANEL		R	\$1,140.20	X
1PC	REAR FLOOR PANEL TOP BOARD		11	\$688.50	X
1PC	REAR FENDER INNER TRIM BOARD		11	\$681.10	X
1PC	REAR FENDER		11	\$1,099.20	X
1PC	REAR ANTENNA SENSOR		11	\$290.50	X
1PC	REAR BUZZLE SENSOR		11	\$288.50	X
				\$14,551.80	

(202)

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	shorted	\$280.00	200
1PC	REAR END PANEL SEALANT	ner	\$50.00	✓
1PC	REAR WINDSCREEN SEALANT	ner	\$50.00	40
1SET	REAR FLOOR PANEL INSULATOR	11	\$300.00	X
1SET	REAR REVERSE CAMERA	11	\$380.00	X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY RUST PROOFING	\$120.00	60

LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$1,500.00 700

\$1,500.00 1080

TOTAL

\$19,331.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-6332-1
207
8065-68
-7835-68