



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:	JSE 6680
MAKE & MODEL:	TOYOTA CAMRY
MILEAGE:	
TYRE:	
CHASSIS NUM:	

ATTN	NO	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING X NN	1	\$691.00.
	2	BOOTLID / 00 890 ✓	1	\$1,679.00.
	3	BOOTLID CENTER GARNISH X NN	1	\$419.00
	4	BOOTLID LOGO (TOYOTA) / NC	1	\$58.00 ✓
	5	BOOTLID EMBLEM (CAMRY) / NC	1	\$79.00
	6	BOOTLID EMBLEM (2.0) / NC	1	\$81.00
	7	BOOTLID EMBLEM (G) / NC	1	\$76.00
	8	BOOTLID EMBLEM (RH) (X) / NC	1	\$76.00
	9	BOOTLID EMBLEM (D-45) / NC	1	\$88.00
	10	BOOTLID LAMP (L+R) X NN	2	\$2,486.00
	11	BOOTLID LAMP CHROME (L+R) X NN	2	\$748.00
	12	BOOTLID HANDLE CHROME X NN	1	\$679.00
	13	BOOTLID HANDLE SWITCH X NN	1	\$589.00
	14	BOOTLID CARPLATE LAMP (L+R) X NN	2	\$246.00
	15	BOOTLID LOCK / BT 220 ✓	1	\$879.00
	16	BOOTLID LOCK COVER X NN	1	\$379.00
	17	BOOTLID LOCK CATCH X NN	1	\$103.00
	18	BOOTLID INNER TRIM X NN	1	\$673.00.
	19	BOOTLID HINGE (L+R) X NN	2	\$578.00.
	20	BOOTLID STOPPER (L+R) X NN	2	\$148.00
	21	BOOTLID WEATHERSTRIP / TN 180 ✓	1	\$399.00.
	22	TAIL LAMP (L+R) X NN	2	\$2,574.00
	23	TAIL LAMP CHROME (L+R) X NN	2	\$105.00
	24	TAIL LAMP PANEL (L+R) X NN	2	\$84.00
	25	REAR BUMPER / 00 580 ✓	1	\$1,379.00
	26	REAR BUMPER RETAINER (L+R) / BR 256 ✓	2	\$428.00
	27	REAR BUMPER CENTER BRACKET (L+R) X NN	2	\$111.00.
	28	REAR BUMPER REINFORCEMENT BAR ? / 00 420 ✓	1	\$1,009.00
	29	REAR BUMPER REINFORCEMENT BRACKET (L+R) X NN	2	\$478.00
	30	REAR BUMPER BEAM X NN	1	NIL.
	31	REAR BUMPER SPONGE ? X NN	1	NIL.
	32	REAR BUMPER REVERSE SENSOR SET / BR (2 pc) 300 ✓	4	\$1,408.00
	33	REAR BUMPER UNDERCOVER ? X NN	1	\$689.00
	34	REAR FENDER (L+R) X NN	2	\$3894.00
	35	REAR FENDER INNER TRIM (L+R) X NN	2	\$2004.00
	36	REAR FENDER COWLING (L+R) X NN	2	\$684.00.
	37	END PANEL X R	1	\$1,1374.00
	38	END PANEL TOP GARNISH ? / BR 220 ✓	1	\$389.00
	39	SPAREWHEEL PANEL X NN	1	\$1,978.00
	40	SPAREWHEEL PANEL TOP BOARD X NN	1	\$485.00

41	SPAREWHEEL PANEL TOP SIDE BOARD (L+R) X NN	2	\$ 86.00
42	SPAREWHEEL PANEL TOP BOARD TOP MAT X NN	1	\$ 341.00
43	EXHAUST PIPE X NN	1	\$ 976.00
44	EXHAUST GASKET X NN	1	\$ 174.00
45	EXHAUST BRACKET (L+R) X NN	2	\$ 96.00
46	EXHAUST HEAT SHIELD X NN	1	\$ 381.00

3404

-25%

SUBTOTAL

\$ -

2553

LESS 25%

\$ -

PARTS TOTAL

\$ -

SPECIAL NETT		QTY	PRICE
1	REAR WINDSCREEN SEALANT X NN	1	\$ 120.00
2	BOOTLID INNER TRIM CLIPS X NN	10	\$ 100.00
3	BOOTLID PROTECTOR STRIP X NN	1	\$ 400.00
4	REAR CARPLATE X NN	1	\$ 250.00
5	REAR CARPLATE FRAME X NN	1	\$ 120.00
6	REVERSE CAMERA X NN	1	\$ 850.00
7	REAR BUMPER CLIPS / MK 30 ✓	10	\$ 100.00
8	REAR BUMPER LOWER / CKH 700 ✓	1	\$ 3,000.00
9	REAR BUMPER LOWER REFLECTOR (L+R) X NN	2	\$ 500.00
10	REAR FENDER SEALANT X NN	2	\$ 600.00
11	REAR FENDER INNER TRIM CLIPS X NN	20	\$ 200.00
12	REAR FENDER COWLING CLIPS X NN	20	\$ 200.00
13	END PANEL SEALANT X NN	1	\$ 250.00
14	END PANEL TOP GARNISH CLIPS / MK 10 ✓	10	\$ 100.00
15	SPAREWHEEL PANEL SEALANT X NN	1	\$ 350.00
760			
SPECIAL NETT TOTAL			\$ 7,140.00

LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 600	1	\$ 3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 600	1	\$ 3,300.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 30	1	\$ 400.00
4	TO RNR REAR WINDSCREEN X	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM X	1	\$ 400.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS X	1	\$ 800.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 30	1	\$ 150.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS X	1	\$ 450.00
9	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION X	1	\$ 150.00
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 30	1	\$ 150.00
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. X	1	\$ 800.00
12	TO DO WATER LEAK TEST. 30	1	\$ 120.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD X	1	\$ 450.00

Steve (LKK) ML ML 1320

16/10/20, 11.00am

L/S. By AC SP

4 days

TOTAL

\$ 11,170.00

GRAND TOTAL COST

\$ 18,310.00

2553

760

1320

= 4633

L/S - 3706.40

= 3700

52982