

ASS. REQ. BY:

Steve

REF:

CS/CT120011210/ETd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JSE 6680

Yr Regn:

22/6/17

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

c.c 1998

Colour:

Black

A/C:

Insured / Std / NI / N

Sp. Reading

156104

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

PNI 53DK 5100003415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

10/10/20

D.O.A.

16/10/20

Survey held at

RICO 60

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

lump sum 3700,4days red:49282;93%

Date/Time, File Pass to?



: Prel. Report



: Final Report

()

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$


Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.B. / P.



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

JSE 6680
TOYOTA CAMRY

ATTN:			
NO.	DESCRIPTION PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING X	1	
2	BOOTLID / <i>DN</i>	1	
3	BOOTLID CENTER GARNISH X	1	
4	BOOTLID LOGO (TOYOTA) / <i>NP</i>	1	
5	BOOTLID EMBLEM (CAMRY) / <i>NP</i>	1	
6	BOOTLID EMBLEM (2.0) / <i>NP</i>	1	
7	BOOTLID EMBLEM (G) / <i>NP</i>	1	
8	BOOTLID EMBLEM (RH) (X) / <i>NP</i>	1	
9	BOOTLID EMBLEM (D-45) / <i>NP</i>	1	
10	BOOTLID LAMP (L+R) X	2	
11	BOOTLID LAMP CHROME (L+R) X	2	
12	BOOTLID HANDLE CHROME X	1	
13	BOOTLID HANDLE SWITCH X	1	
14	BOOTLID CARPLATE LAMP (L+R) X	2	
15	BOOTLID LOCK / <i>BT</i>	1	
16	BOOTLID LOCK COVER X	1	
17	BOOTLID LOCK CATCH X	1	
18	BOOTLID INNER TRIM X	1	
19	BOOTLID HINGE (L+R) X	2	
20	BOOTLID STOPPER (L+R) X	2	
21	BOOTLID WEATHERSTRIP / <i>TN</i>	1	
22	TAIL LAMP (L+R) X	2	
23	TAIL LAMP CHROME (L+R) X	2	
24	TAIL LAMP PANEL (L+R) X	2	
25	REAR BUMPER / <i>DD</i>	1	
26	REAR BUMPER RETAINER (L+R) / <i>BR</i>	2	
27	REAR BUMPER CENTER BRACKET (L+R) X	2	
28	REAR BUMPER REINFORCEMENT BAR ?	1	
29	REAR BUMPER REINFORCEMENT BRACKET (L+R) X	2	
30	REAR BUMPER BEAM X	1	
31	REAR BUMPER SPONGE ?	1	
32	REAR BUMPER REVERSE SENSOR SET / <i>BR</i>	4	
33	REAR BUMPER UNDERCOVER ?	1	
34	REAR FENDER (L+R) X	2	
35	REAR FENDER INNER TRIM (L+R) X	2	
36	REAR FENDER COWLING (L+R) X	2	
37	END PANEL X <i>R</i>	1	
38	END PANEL TOP GARNISH ?	1	
39	SPAREWHEEL PANEL X	1	
40	SPAREWHEEL PANEL TOP BOARD X	1	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

41	SPAREWHEEL PANEL TOP SIDE BOARD (L+R) X		2	
42	SPAREWHEEL PANEL TOP BOARD TOP MAT X		1	
43	EXHAUST PIPE X		1	
44	EXHAUST GASKET X		1	
45	EXHAUST BRACKET (L+R) X		2	
46	EXHAUST HEAT SHIELD X		1	
		SUBTOTAL		\$ -
		LESS 25%		\$ -
		PARTS TOTAL		\$ -
		SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT X		1	\$ 120.00
2	BOOTLID INNER TRIM CLIPS X		10	\$ 100.00
3	BOOTLID PROTECTOR STRIP X		1	\$ 400.00
4	REAR CARPLATE X		1	\$ 250.00
5	REAR CARPLATE FRAME X		1	\$ 120.00
6	REVERSE CAMERA X		1	\$ 850.00
7	REAR BUMPER CLIPS / MK 50		10	\$ 100.00
8	REAR BUMPER LOWER / CRU		1	\$ 3,000.00
9	REAR BUMPER LOWER REFLECTOR (L+R) X		2	\$ 500.00
10	REAR FENDER SEALANT X		2	\$ 600.00
11	REAR FENDER INNER TRIM CLIPS X		20	\$ 200.00
12	REAR FENDER COWLING CLIPS X		20	\$ 200.00
13	END PANEL SEALANT X		1	\$ 250.00
14	END PANEL TOP GARNISH CLIPS X ?		10	\$ 100.00
15	SPAREWHEEL PANEL SEALANT X		1	\$ 350.00
		SPECIAL NETT TOTAL		\$ 7,140.00
		LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 600		1	\$ 3,600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 600		1	\$ 3,300.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA 30		1	\$ 400.00
4	TO RNR REAR WINDSCREEN X		1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM X		1	\$ 400.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS X		1	\$ 800.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. 30		1	\$ 150.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS X		1	\$ 450.00
9	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION X		1	\$ 150.00
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION 30		1	\$ 150.00
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. X		1	\$ 800.00
12	TO DO WATER LEAK TEST. 30		1	\$ 120.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD X		1	\$ 450.00
	Steve (LKK) WNL ML			
	16/10/20, 11 Man			
	L/S, By AC SN			
	4 days			
		TOTAL		\$ 11,170.00
		GRAND TOTAL COST		\$ 18,310.00



**SINGAPORE
POLICE FORCE**



T/20201010/2089

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No: T/20201010/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2020 20:27	Vide Report No.:	Station Diary No.: 75
--	------------------	--------------------------

Informant's Particulars

Name of Informant: QUEK WEE KIAT			Address: C/O 810 Geylang Road #15-05 City Plaza SINGAPORE 409286		
ID Type / ID No.: FIN NO / G6787487R			Contact No.: Home/Office: Mobile: 93292616		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 35	Date of Birth: 20/09/1985	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Sales			Driving Licence Information: Class: 3 Date of Expiry: 20/09/2023		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 10/10/2020 17:50	Type of Location: Straight Road
Location: BEDOK NORTH ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
JSE6680	Car				Slightly Damaged	0
SMK297Z	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20201010/2089

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

241
Report No. T/20201010/2089

CONTINUATION OF REPORT

Name	QUEK WEE KIAT	ID No.	G6787487R
Related Vehicle	JSE6680 (Car)	Contact No.	93292618
Hospital/Clinic	OUR FAMILY PHYSICIAN CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 20/09/2023
Date Treatment	10/10/2020	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Name	MOHAMAD NAZERI BIN JOHAN	ID No.	S7834149A
Related Vehicle	SMK297Z (Car)	Contact No.	87848667
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 10/10/2020 at about 1750hrs, I was driving my Black Toyota Camry bearing plate JSE6680 along Bedok North Road on the middle lane of a 3 lane road. I was approaching a traffic light and it was red at that point of time. As such, I slowed down before coming to a stop. Out of nowhere, I felt an impact from the rear of my vehicle. I pull my handbrake, on my vehicle hazard lights and alighted the vehicle to take a look.

When I alighted my vehicle, I saw that I was knocked at the rear by a Silver Honda bearing plate SMK297Z. The owner of the vehicle alighted and ask why did I suddenly stop my vehicle. I told him that in front of me had stop that is why I also stopped. We both exchanged particulars, took some photos of the incident and our vehicle before we left.

I took my vehicle to a workshop to make a check before going to see a doctor myself. From what I can see, the damages on my vehicle are my rear bumper and the rear boot are dented. I would like to report the incident and my vehicle before we left. I am currently suffering from some neck and back pain and have gotten 5 days MC from 10/10/2020.



**SINGAPORE
POLICE FORCE**



1/10/2010 10:27:09

3 of 3

Report No: 1/202010102709

Police Station Of Origin
Sembawang N P C
4 Sembawang Crescent SINGAPORE
757633
Tel No 1800-5549999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording Report:

L/

Sgt 2 YU JUNRONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:

10/10/2020 20:27

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt YONG BIEU LUI

Contact No. 65476151

Of Case:

Authentication Stamp

Singapore Police Force



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

EB

No. Pendaftaran	: JSE6680
No. ID	: 850920015311
Nama Pemunya Berdaftar	: QUEK WEE KIAT
Alamat	: 12 JLN DAMAI SERENE PARK 80300 JOHOR BAHRU JOHOR
No. Chasis/No. Enjin	: PN153DK5100003415 / 6ARP297390
Buatan>Nama Model	: TOYOTA / CAMRY 2.0G X AT
Keupayaan Enjin	: 1998
Bahan Bakar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat	: MOTOKAR / 2017
Tarikh Pendaftaran	: 22/06/2017
B D M/B.G K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -