

FASTECH AUTO PTE LTD  
BLK 1 KAKI BUKIT AVE 6  
#01-48, AUTO BAY  
SINGAPORE 417883

sub carline

Not Authorized  
near  
d/c \$4350/  
575

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

VEHICLE No: SJT 2402L

|      |                                     |                      |          |             |     |
|------|-------------------------------------|----------------------|----------|-------------|-----|
| 1PC  | BOOTLID                             |                      | R        | \$1,055.10  | X   |
| 2PCS | BOOTLID HINGES @\$190.10            |                      | 11       | \$380.20    | X   |
| 1PC  | BOOTLID INNER TRIM                  |                      | 11       | \$459.10    | X   |
| 1PC  | BOOTLID INNER LOCK                  |                      | 11       | \$399.10    | X   |
| 1PC  | BOOTLID WEATHERSTRIP                | 266.50               | 11/10/11 | \$299.90    | /   |
| 1PC  | BOOTLID REAR LOGO                   |                      | 1A       | \$85.10     | X   |
| 1PC  | BOOTLID 'AXIO' EMBLEM               |                      | 111      | \$46.50     | /   |
| 1PC  | BOOTLID 'X' EMBLEM                  |                      | 111      | \$50.00     | /   |
| 1PC  | BOOTLID OUTER HANDLE                |                      | 11       | \$332.10    | X   |
| 1PC  | REAR BUMPER                         | 681.10               | Re/To/11 | \$1,055.10  | /   |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$65.00 |                      | 11/10/11 | \$130.00    | 1PC |
| 2PCS | REAR BUMPER BRACKETS @\$105.00      |                      | 11/10/11 | \$210.00    | 1PC |
| 1SET | REAR BUMPER CLIPS                   |                      | 111      | \$50.00     | /   |
| 1PC  | REAR END PANEL                      |                      | 111      | \$889.10    | /   |
| 1PC  | REAR END PANEL TOP GARNISH          |                      | 111      | \$299.90    | /   |
| 1PC  | REAR FLOOR PANEL                    |                      | 11       | \$1,045.10  | X   |
| 1PC  | REAR FLOOR PANEL TOP BOARD          | 645.10               | 111      | \$650.10    | /   |
| 2PCS | TAILLAMPS @\$650.10                 | 566.10 x 2 = 1132.20 | 111      | \$1,300.20  | /   |
| 2PCS | TAILLAMP HOUSING PANELS @\$450.10   |                      | 11       | \$900.20    | X   |
| 2PCS | REAR FENDER INNER TRIMS @\$422.10   |                      | 11       | \$844.20    | X   |
| 2PCS | REAR FENDERS @\$995.10              |                      | 11       | \$1,990.20  | X   |
|      |                                     |                      |          | \$12,471.20 |     |

|      |                             |  |        |          |     |
|------|-----------------------------|--|--------|----------|-----|
| 1SET | REAR BUMPER REVERSE SENSOR  |  | Should | \$280.00 | 200 |
| 1PC  | REAR END PANEL SEALANT      |  | 111    | \$50.00  | /   |
| 1SET | REAR FLOOR PANEL INSULATOR  |  | 11     | \$380.00 | X   |
| 1PC  | REAR LICENCE PLATE W/HOLDER |  | 11     | \$50.00  | X   |

|                                           |             |      |
|-------------------------------------------|-------------|------|
| TO CHECK WIRING                           | \$50.00     | 30   |
| TO DISMANTLE & REPLACED REVERSE SENSOR    | \$80.00     | 50   |
| TO TRANSFER BOOTLID COMPONENTS            | \$80.00     | X    |
| TO SPRAY RUST PROOFING                    | \$120.00    | 50   |
| TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | \$120.00    | 80   |
| TO DISMANTLE & REFIX REAR EXHAUST         | \$100.00    | X    |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$1,800.00  | 800  |
| TO PUTTY & SPRAY PAINTING                 | \$1,600.00  | 1000 |
| TOTAL                                     | \$17,181.20 |      |

P-4239.40  
242  
23172.80  
S.N-250  
L-2010

4432.80  
4346.24

P-4280.40  
50%  
2115.2  
250  
2010  
4375