

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31474

Vehicle Insured : GBH 9689 M
Accident Date : 13-Oct-2020

Date : 14-Oct-2020

Our Ref : 020485 (AIG ASIA) / QUEK

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

Not Authorised

Resurvey B & paint

8 days

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT (2019) SMM2732K
=====

1 pc	front bumper		<i>Bt/can</i> 504.60	✓
1 pc	n/s front bumper side retainer		<i>D/I</i> 10.40	✓
1 pc	n/s front bumper fog cover		<i>nd/wt</i> 29.00	✓
1 pc	front bumper reinforcement		213.00	?
1 pc	front bumper lower centre grille		<i>D/I</i> 137.90	✓
1 pc	n/s front bumper lower centre grille side garnish		8.50	?
10 pcs	front bumper clips	@ S\$ 3.50	<i>nc</i> 35.00	✓
1 pc	n/s headlamp assy		558.60	
1 pc	n/s headlamp lower bracket		27.70	
2 pcs	rear number plate lamp (LH/RH)	@ S\$ 32.80	65.60	
1 pc	rear bumper		<i>Bt</i> 492.60	✓
2 pcs	rear bumper side retainer (LH/RH)	@ S\$ 16.90	<i>D/I</i> 33.80	✓
10 pcs	rear bumper clips	@ S\$ 3.50	<i>nc</i> 35.00	✓
1 pc	rear bumper lower centre garnish		<i>wap</i> 65.00	✓
2 pcs	rear bumper lower side garnish (LH/RH)	@ S\$ 21.20	42.40	?
1 pc	tailgate		<i>Bt</i> 830.60	✓
1 pc	tailgate glass		<i>shorter</i> 626.60	✓
1 pc	tailgate glass moulding -(set)		<i>nc</i> 95.60	✓
1 pc	tailgate lock		<i>nd</i> 78.90	✓
1 pc	tailgate lock catch		<i>nc</i> 24.70	X
1 pc	tailgate outer garnish		<i>CM</i> 105.50	✓
1 pc	tailgate outer handle		58.30	?
2 pcs	tailgate hinges (LH/RH)	@ S\$ 33.20	<i>nc</i> 66.40	X
2 pcs	tailgate damper (LH/RH)	@ S\$ 94.00	<i>sm</i> 188.00	X
1 pc	tailgate wiper arm		58.00	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GBH 9689 M
Our Ref : 020485

Page : 2
No. : 31474

1 pc	tailgate wiper arm screw cap		CM	8.00	—
1 pc	tailgate wiper motor			81.00	7
2 pcs	tailgate lamp (LH/RH)	@ S\$ 89.20	SL	178.40	X
1 pc	tailgate inner pocket handle			8.50	7
1 pc	tailgate inner trim board			53.70	7
12 pcs	tailgate inner trim board clips	@ S\$ 3.50		42.00	7
1 pc	tailgate weatherstrip		DI	92.30	✓
1 pc	tailgate logo		SL	15.70	—
1 pc	tailgate 'JAZZ' emblem		SL	18.90	—
1 pc	tailgate wiper blade		SL	41.10	X
2 pcs	taillamp assy (LH/RH)	@ S\$244.60	CM	489.20	✓
2 pcs	taillamp panel (LH/RH)	@ S\$ 76.80		153.60	7
2 pcs	taillamp clips	@ S\$ 3.50	SL	7.00	—
1 pc	rear end panel			328.60	7
1 pc	rear end panel top garnish			60.80	7
1 pc	o/s rear fender		R	570.50	X
1 pc	o/s rear fender 1/4 glass moulding		SL	20.60	X
1 pc	o/s rear fender inner trim lining			169.00	7
11 pcs	o/s rear fender inner trim lining clips	@ S\$ 3.50		38.50	7
1 pc	spare tyre panel		R	683.30	X
1 pc	spare tyre panel sponge compartment		CM	117.40	—
1 pc	spare tyre panel top lid		SL	189.90	X
1 pc	o/s spare tyre panel side panel			92.30	7
1 pc	rear exhaust box		R	430.10	X
1 pc	reverse camera			1,041.10	7
1 pc	rear shelf cover		SL	228.90	X
				9,552.10	
Less 20% :				-1,910.42	
				7,641.68	

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GBH 9689 M
Our Ref : 020485

Page : 3
No. : 31474

1 pc rear number plate
1 pc rear bumper 'L' bracket
1 pc tailgate glass sealant
1 pc tailgate glass damping seal
3 pcs tailgate '1' and '9' sticker @ S\$ 10.00
1 pc tailgate 'thank you for your
patience' sticker
1 pc o/s rear fender 1/4 glass
sealant
1 pc o/s rear fender 1/4 glass
damping seal

nd 40.00 sn ✓
nd 30.00 sn ✓
nd 40.00 sn ✓
nd 20.00 sn ✓
nd 30.00 sn ✓
nd 150.00 sn ✓
nd 40.00 sn X
nd 20.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1000
1,600.00

To remove and renew rear windscreen
glass and conduct water leak test.

120.00 ✓

To remove and refit right rear
fender 1/4 glass and conduct water
leak test

nd 120.00 X

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 *1000*

To apply undersealing

160.00 *600*

To remove and renew exhaust
silencer box

60.00 ?

To transfer tailgate's fittings

80.00 *600*

To putty and respray on affected
portions.

1,650.00 *12000*

Con't Page 4 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GBH 9689 M
Our Ref : 020485

Page : 4
No. : 31474

To focus Headlamps and Taillamps.

To check front and rear lighting
operation and rewiring

40/ 60.00

Total : S\$11,981.68
=====

Singapore Dollars Eleven Thousand Nine Hundred
and Eighty One and Cents Sixty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.