



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

Reg: 201828067M

11723 (Ae)

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

(MOTOR CLAIMS DEPARTMENT)

Xiao Tong

Address: NO 8, SHENTON WAY, #24-01

AXA TOWER, S(068811)

Telephone: 68804888

Fax: 68804740

Email: motor.survey@axa.com.sg

Make/ Model : HYUNDAI AVANTE

Date: 13.10.2020

Chassis No : KMHD841CMKU891134

Vehicle No: SML3586P

Date/Time of Accide 12.10.2020/ 0730

Reg date : 16.05.2019

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Deband</i>	1	\$ 658.20	528	\$ ✓ 658.20
2	FRONT BUMPER TOP RUBBER SEAL <i>not here</i>	1	\$ 85.20		\$ + 85.20
3	FRONT BUMPER TOP BRACKET LH <i>not here</i>	1	\$ 98.60		\$ + 98.60
4	FRONT BUMPER SIGNAL LAMP LH <i>not here</i>	1	\$ 165.80		\$ ✓ 165.80
5	FRONT BUMPER RETAINER LH <i>not here</i>	1	\$ 86.90		\$ ✓ 86.90
6	FRONT BUMPER AIR GUIDE LH <i>not here</i>	1	\$ 125.80		\$ ✓ 125.80
7	FRONT BUMPER SIDE STRIP LH <i>not here</i>	1	\$ 92.60		\$ ✓ 92.60
8	FRONT BUMPER SIDE COVER LH <i>not here</i>	1	\$ 98.60		\$ ✓ 98.60
9	FRONT BUMPER LOWER LIP <i>not here</i>	1	\$ 295.60		\$ + 295.60
10	FRONT RESONATOR BOX <i>not here</i>	1	\$ 158.30		\$ + 158.30
11	FRONT ENGINE UNDER COVER <i>not here</i>	1	\$ 356.80		\$ + 356.80
12	FRONT BUMPER SPONGE <i>not here</i>	1	\$ 225.60		\$ + 225.60
13	FRONT BUMPER LOWER STIFFENER <i>not here</i>	1	\$ 175.20		\$ ✓ 175.20
14	FRONT BUMPER REINFORCEMENT <i>not here</i>	1	\$ 589.50		\$ + 589.50
15	FRONT BUMPER RADIATOR GRILLE <i>not here</i>	1	\$ 1,218.60	628	\$ + 1,218.60
16	FRONT BUMPER NUMBER PLATE BASE <i>not here</i>	1	\$ 65.30		\$ + 65.30
17	FRONT SUPPORT PANEL TOP GARNISH <i>not here</i>	1	\$ 202.50		\$ + 202.50
18	FRONT SUPPORT PANEL <i>not here</i>	1	\$ 987.50		\$ + 987.50
19	FRONT RADIATOR <i>not here</i>	1	\$ 526.80		\$ + 526.80
20	FRONT CONDENSER <i>not here</i>	1	\$ 746.50		\$ + 746.50
21	FRONT HEADLAMP LH <i>not here</i>	1	\$ 3,035.20	2396	\$ ✓ 3,035.20
22	FRONT HEADLAMP BRACKET LH <i>not here</i>	1	\$ 98.60		\$ + 98.60
23	FRONT BONNET <i>not here</i>	1	\$ 1,971.20		\$ + 1,971.20
24	FRONT BONNET INSULATOR <i>not here</i>	1	\$ 385.90		\$ + 385.90
25	FRONT FENDER LH <i>not here</i>	1	\$ 1,227.70		\$ + 1,227.70
26	FRONT FENDER INNER COWLING LH <i>not here</i>	1	\$ 189.30		\$ + 189.30
27	FRONT RIM LH <i>not here</i>	1	\$ 982.50		\$ + 982.50
28	FRONT KNUCKLE ARM LH <i>not here</i>	1	\$ 423.50		\$ + 423.50
29	FRONT WHEEL HUB BEARING LH <i>not here</i>	1	\$ 458.90		\$ + 458.90
30	FRONT STABILIZER LINK LH <i>not here</i>	1	\$ 158.90		\$ + 158.90
31	FRONT STABILIZER BAR LH <i>not here</i>	1	\$ 298.70		\$ + 298.70

32	FRONT STABILIZER BUSH LH <i>324</i>	1	\$ 48.90	\$ <i>x</i> 48.90
33	FRONT ABSORBER LH <i>3m</i>	1	\$ 398.70	\$ <i>x</i> 398.70
34	FRONT ABSORBER TOP MOUNTING LH <i>neu</i>	1	\$ 158.90	\$ <i>x</i> 158.90
35	FRONT LOWER ARM LH <i>324</i>	1	\$ 345.20	\$ <i>x</i> 345.20
36	SIDE MIRROR ASSY LH <i>free</i>	1	\$ 1,054.60	\$ <i>x</i> 1,054.60
37	SIDE ROCKER PANEL LH <i>neu</i>	1	\$ 1,764.80	\$ <i>x</i> 1,764.80
Total List Price Cost				\$ 19,961.40
PARTS DISCOUNT 20%				\$ 15,969.12

4621.10
3696.88

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT FENDER INNER COWLING CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>x</i> 30.00
2	FRONT BUMPER CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>✓</i> 30.00
3	FRONT NUMBER PLATE WITH CASING <i>neu</i>	1 SET	\$ 50.00	\$ <i>x</i> 50.00
4	SUPPORT PANEL TOP GARNISH CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>x</i> 30.00
5	FRONT ENGINE UNDERCOVER CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>x</i> 30.00
6	FRONT HEADLAMP CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>10</i> 30.00
7	FRONT ENGINE UNDERCOVER CLIPS <i>neu</i>	1 SET	\$ 30.00	\$ <i>x</i> 30.00
Total Special Nett Items				\$ 230.00

40

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER	\$ 1,400.00

400.

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00

400.

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ <i>40</i> 150.00
TO REMOVE /REFIT FRONT CONDENSER & TOP UP GAS FOR SUPPORT PANEL REPLACEMENT	\$ <i>x</i> 120.00
LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE	\$ <i>x</i> 180.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER	\$ <i>x</i> 120.00
TO REMOVE/ REFIT WIRING CHECKS FOR HEADLAMP	\$ <i>30</i> 150.00
Total Others Cost	\$ 720.00

GRAND TOTAL

\$ 19,719.12

870

Adrian Lj
P/P 16/10/20

04 Days.

total: 4606.88

CP/P)

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7471

Email: allangoh.cas@gmail.com

Fax : 6509 9501

- KKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - All prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: