

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5990Z****AAD2010-060***Not Authorised*  
*U/Eng &*

Vehicle No.:

Chassis No.:

Vehicle Make:

**14 OCT 2020**

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC5990Z**

VF1ABL15AUC281518

RENAULT

LATITUDE

13/10/2020

**LONPAC**

23/03/2015

	<b>PART</b>
1	1 BUMPER COVER REAR
2	1 BUMPER LOWER REAR
3	1 BUMPER BRACKET CTR REAR
4	1 BUMPER BRACKET SIDE RH REAR
5	1 BUMPER RETAINER RH REAR
7	1 BUMPER BRACKET SIDE LH REAR
8	1 BUMPER RETAINER LH REAR
10	1 BUMPER BEAM REAR
11	1 BUMPER BEAM BRACKET LH REAR
12	1 BUMPER BEAM BRACKET RH REAR
13	1 OUTER PANEL REAR (End Panel)
14	1 OUTER PANEL REAR (End Panel)TRIM
15	1 BOOT REAR
16	1 BOOT BADGE 'RENAULT'
17	1 BOOT BADGE
18	1 TAILLAMP LH
19	1 TAILLAMP RH

	<b>LIST</b>	
\$	<i>Bz</i>	561.70 ✓
\$	<i>Bu</i>	411.90 ✓
\$	<i>SL</i>	98.10 X
\$	<i>SL</i>	82.10 X
\$	<i>SL</i>	59.80 X
\$	<i>SL</i>	80.80 X
\$	<i>SL</i>	54.20 X
\$	<i>Bu</i>	547.80 ✓
\$		114.50 ?
\$		114.50 ?
\$	<i>Bz</i>	745.80 ✓
\$	<i>SL</i>	404.56 ✓
\$	<i>Bz</i>	1,677.20 ✓
\$	<i>SL</i>	82.40 ✓
\$	<i>SL</i>	95.80 ✓
\$	<i>CM</i>	401.40 ✓
\$	<i>SL</i>	401.40 X
\$		<b>5,933.96</b>
10% \$		<b>593.40</b>
\$		<b>5,340.56</b>

**Specical Nett**

1	1SET PARKING AID
2	1SET REAR BUMPER CLIP
3	1SET BUMPER BRACKET CTR CLIP
4	1SET BUMPER BRACKET SIDE CLIP RH RR
5	1SET BUMPER RETAINER RH CLIP RR
6	1SET BUMPER BRACKET SIDE CLIP LH RR

\$	<i>SL</i>	700.00 X
\$	<i>SL</i>	66.00 ✓
\$	<i>SL</i>	33.00 X
\$	<i>SL</i>	10.00 X
\$	<i>SL</i>	20.00 X
\$	<i>SL</i>	10.00 X

**Trans-cab Auto Services Pte Ltd**

AAD2010-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5990Z**

7 1SET BUMPER RETAINER CLIP LH RR	\$	<i>Nn</i>	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	<i>Nn</i>	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	<i>Nn</i>	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	<i>Nn</i>	17.82	X
14 1 REAR BOOT STICKER 'Trans-cab'	\$	<i>Nn</i>	80.00	3012
15 1 REAR BOOT STICKER '6555-3333'	\$	<i>Nn</i>	80.00	3012
<b>TOTAL</b>	<b>\$</b>		<b>325.82</b>	
<b>TOTAL PARTS</b>	<b>\$</b>		<b>5,666.38</b>	

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$		170.00	601
To reinstall rear bumper parking sensor.	\$		170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	601
To repair and realign rear exhaust pipe.	\$	<i>Nn</i>	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>Nn</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$		170.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5990Z**

**AAD2010-060**

To check steering geometry and computer wheel alignment \$ *220.00* X

To Check Electrical Lighting Concerned. \$ 170.00 *200*

**TOTAL \$ 7,580.00**

**Over All Total \$ 18,586.95**

**(LUMP SUM)**

**Repair Days**

*10 DAYS*  
*5 day*

**For Official Use**

Prepared By : \_\_\_\_\_  
(Accident Dept)

Verify By : \_\_\_\_\_  
(Accident Workshop)

Checked By : \_\_\_\_\_  
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: