

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5990Z**AAD2010-060**

Not Authorised
Clamp @ 4900hr

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

14 OCT 2020**SHC5990Z**

VF1ABL15AUC281518

RENAULT

LATITUDE

13/10/2020

LONPAC

23/03/2015

	PART
1	1 BUMPER COVER REAR
2	1 BUMPER LOWER REAR
3	1 BUMPER BRACKET CTR REAR
4	1 BUMPER BRACKET SIDE RH REAR
5	1 BUMPER RETAINER RH REAR
7	1 BUMPER BRACKET SIDE LH REAR
8	1 BUMPER RETAINER LH REAR
10	1 BUMPER BEAM REAR
11	1 BUMPER BEAM BRACKET LH REAR
12	1 BUMPER BEAM BRACKET RH REAR
13	1 OUTER PANEL REAR (End Panel)
14	1 OUTER PANEL REAR (End Panel)TRIM
15	1 BOOT REAR
16	1 BOOT BADGE 'RENAULT'
17	1 BOOT BADGE
18	1 TAILLAMP LH
19	1 TAILLAMP RH

	LIST
\$	B ₁ 561.70 —
\$	B ₂ 411.90 —
\$	S ₁ 98.10 X
\$	S ₂ 82.10 X
\$	S ₃ 59.80 X
\$	S ₄ 80.80 X
\$	S ₅ 54.20 X
\$	B ₃ 547.80 —
\$	R 114.50 X
\$	R 114.50 X
\$	B ₄ 745.80 —
\$	M 404.56 —
\$	B ₅ 1,677.20 —
\$	N ₁ 82.40 —
\$	N ₂ 95.80 —
\$	CM 401.40 —
\$	S ₆ 401.40 X
\$	5,933.96
10% \$	593.40
\$	5,340.56

Specical Nett

1	1SET PARKING AID
2	1SET REAR BUMPER CLIP
3	1SET BUMPER BRACKET CTR CLIP
4	1SET BUMPER BRACKET SIDE CLIP RH RR
5	1SET BUMPER RETAINER RH CLIP RR
6	1SET BUMPER BRACKET SIDE CLIP LH RR

\$	S ₇ 700.00 X
\$	N ₃ 66.00 —
\$	N ₄ 33.00 X
\$	N ₅ 10.00 X
\$	N ₆ 20.00 X
\$	N ₇ 10.00 X

Trans-cab Auto Services Pte Ltd

AAD2010-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5990Z

7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	<i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	<i>✓</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	<i>X</i>
14	1 REAR BOOT STICKER 'Trans-cab'	\$	<i>nn</i>	80.00	<i>301m</i>
15	1 REAR BOOT STICKER '6555-3333'	\$	<i>nn</i>	80.00	<i>301m</i>
TOTAL		\$		325.82	
TOTAL PARTS		\$		5,666.38	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2010-060

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5990Z

To check steering geometry and computer wheel alignment \$ *220.00* X

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ 7,580.00

Over All Total \$ 18,586.95

(LUMP SUM)

Repair Days

10 DAYS
5 day

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: