

ASS. REQ. BY:

REF:

F02 / 20011233 / KK

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 1/2 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HD 5176C

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

207687

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3F4 203078485

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/10/20

D.O.I.

15/10/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11 @ 752.23

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Wharfed
8752-23

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5176C

AAD2010-064

15 OCT 2020

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD5176C

JTDKB3FU203078485

TOYOTA

PRIUS

14/10/2020

FIRST CAPITAL

19/12/2018

PART		LIST	
1	COVER, REAR BUMPER	\$	442.60 X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70 X
1	GUARD, REAR BUMPER, CENTER	\$	576.30 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	117.70
1	PANEL SUB-ASSY, BACK DOOR	\$	1,147.80
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30
1	FILLER, REAR BUMPER EXTENSION, RH	\$	123.70
1	LENS AND BODY, REAR LAMP, LH	\$	502.00
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	443.30
1	LENS AND BODY, REAR LAMP, RH	\$	502.00
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	451.80
TOTAL		\$	5,290.20
25%		\$	1,322.55
		\$	3,967.65

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	85.00	
1 REAR BUMPER PROTECTOR	\$	180.00	
1 REAR BUMPER RETAINER CLIP	\$	75.00	
1SET TAILLAMP CLIP	\$	50.00	
2 WINDSCREEN SEALANT	\$	150.00	
1SET REAR FENDER LINER CLIP	\$	75.00	
TOTAL	\$	1,315.00	

Trans-cab Auto Services Pte Ltd

AAD2010-064

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5176C

TOTAL PARTS	\$	5,282.65
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	<i>100</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>220</i>
To reinstall rear bumper parking sensor.	\$	<i>4</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	170.00	X
To Check Electrical Lighting Concerned.	\$	<i>4</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>4</i>	170.00	X

TOTAL	\$	5,100.00
--------------	-----------	-----------------

Over All Total	\$	10,382.65
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days*10 Days**1 1/2 days*

Trans-cab Auto Services Pte Ltd

AAD2010-064

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5176C

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5176C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Oct 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B91590
Chassis No.:	JTDKB3FU203078485
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,031.00
Total Rebate Amount:	\$27,716.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Oct 2020

OK