

Not Notarized

Trans-cab Auto Services Pte Ltd

AAD2010-064

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

15 OCT 2020

SHD5176C

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD5176C

JTDKB3FU203078485

TOYOTA

PRIUS

14/10/2020

FIRST CAPITAL

19/12/2018

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, RH
1	PANEL SUB-ASSY, BACK DOOR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	FILLER, REAR BUMPER EXTENSION, RH
1	LENS AND BODY, REAR LAMP, LH
1	LENS & BODY, REAR COMBINATION LAMP, LH
1	LENS AND BODY, REAR LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, RH

	LIST
\$	442.60 X
\$	332.70 7
\$	576.30 ✓
\$	117.70
\$	1,147.80
\$	650.30
\$	123.70 X
\$	502.00
\$	443.30
\$	502.00
\$	451.80
TOTAL	\$ 5,290.20
25%	\$ 1,322.55
	\$ 3,967.65

Special Nett

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1	REAR BUMPER PROTECTOR
1	REAR BUMPER RETAINER CLIP
1SET	TAILLAMP CLIP
2	WINDSCREEN SEALANT
1SET	REAR FENDER LINER CLIP

\$	700.00	X
\$	85.00	
\$	180.00	
\$	75.00	
\$	50.00	
\$	150.00	
\$	75.00	
TOTAL	\$ 1,315.00	

Trans-cab Auto Services Pte Ltd

AAD2010-064

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5176C

TOTAL PARTS	\$	5,282.65
-------------	----	----------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	100
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	220
To reinstall rear bumper parking sensor.	\$	4	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4	170.00	X
To Check Electrical Lighting Concerned.	\$	4	170.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	4	170.00	X
TOTAL	\$		5,100.00	

Over All Total	\$	10,382.65
----------------	----	-----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days

10 Days

1 1/2 days