

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/SMO20011235/Kyd3e2 SOMPO INSURANCE SINGAPORE PL Ref: 50 RAFFLES PLACE #05-01/06 02-11-2020 Date: SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. XB 8366Y Veh. Inspected **GBJ 2737T** Policy No. Coverage (\$) 0.00 CMTD2003025/THE Excess (\$) 0.00 Claim No. **Assign From GRACE TEO Assign Date** 16/10/2020 2. **Vehicle Particulars & Condition** Make & Model TOYOTA HIACE (A) 2982 c.c **Engine No. HIDDEN** Year of Reg. 2019 JTFHT02P400248019 Chassis No. Colour WHITE 60028 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification NIL GOOD General **Conditions of Tyres** 3. Size Make **Balance** 195 R15X8 **BRIDGESTONE** 3 mm R/H Front Tyre **BRIDGESTONE** L/H Front Tyre 195 R15X8 3 mm R/H Rear Tyre 195 R15X8 **BRIDGESTONE** 8 mm 195 R15X8 **BRIDGESTONE** 8 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. **General Information** 5. Inspect Date / Time 16/10/2020 (11:48 AM) **Accident Date** 15/10/2020 Survey held at 160 SIN MING DRIVE# 05-17 HIAP LEK AUTOMOBILE TRADING Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500

Report Ref No. CS3/SMO20011235/Kyd3e2

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.