



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0752/2020/NS
DATE	:	9-Oct-20
WIP	:	52405

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME	:	MR GOH KIAN HENG ALVIN
ADDRESS	:	BLK 151 RIVERVALE CRESCENT #13-92
TELEPHONE	:	HP +65 81808311
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800012970-02
VEHICLE NO	:	SLW 3344 A
MODEL CODE	:	AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR	:	7/2/2018
ENGINE NO	:	CVK 052016
CHASSIS NO	:	WAUZZZF53JA054678
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	6-Oct-20
PLACE OF ACCIDENT	:	BRADDELL VIEW, BRADDELL HILL CARPARK

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3344 A**

<u>S/N</u>	<u>NATURE OF JOBS</u>		<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	X
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	300.00	X
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$	200.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,400.00	X
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,660.00</u>	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 3344 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	?
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
8	TO DISMANTLE REAR BUMPER, RHS REAR DOOR AND RHS SILL PANEL TRIM. TO RENEW RHS REAR DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	2000
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS REAR DOOR, DOOR HANDLES, RHS SILL PANEL, RHS SILL PANEL TRIM, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 4,000.00	2300 550 x 4 = 2200 Handle = 100 2300
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,312.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 3344 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR FENDER - RH <i>Dented</i>		\$ 2,472.00	✓
2 SIDE WINDOW - RH <i>1st New</i>		\$ 709.00	+
3 REAR DOOR - RH <i>Distorted</i>		\$ 3,091.00	✓
4 REAR DOOR OUTER SEAL - RH <i>NEC</i>	NEC	\$ 220.00	✓
5 BONDING AGENT <i>?</i>	NEC	\$ 47.00	?
6 CLEANING SOLUTION <i>?</i>	NEC	\$ 65.00	?
7 REAR DOOR ATTACHMENT PARTS <i>NEC</i>		\$ 128.00	+
8 REAR DOOR CATCH <i>?</i>		\$ 119.00	?
9 SIDE MEMBER TRIM - RH <i>Repair</i>		\$ 816.00	+
10 SILL MEMBER TRIM ATTACHMENT PARTS <i>NEC</i>		\$ 129.00	+
11 SIDE MEMBER TRIM ADHESIVE TAPES <i>NEC</i>		\$ 210.00	✓
12 REAR ALUMINIUM RIM - RH <i>cut</i>		\$ 1,012.00	✓
13 1/4 GLASS <i>None m</i>	S/N	\$ 100.00	+
14 METAL FILLER POWDER <i>?</i>	S/N	\$ 280.00	✓
15 STONE CHIP <i>NEC</i>	S/N	\$ 180.00	✓
16 CAVITY WAX	S/N	\$ 140.00	✓
17 ACRYLIC SEALANT	S/N	\$ 180.00	✓
18 SUNDRIES <i>?</i>		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 10,198.00	
TOTAL LABOUR CHARGES	:	\$ 13,312.00	
GRAND TOTAL	:	\$ 23,510.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian King -

SURVEYED DATE

: 16/10/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 07 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT