

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0777/2020/NS
DATE : 2-Oct-20
WIP : 51718

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS QIN XIANG
ADDRESS : 33 PASIR RIS DRIVE 3
#05-04
SINGAPORE 519492
TELEPHONE : HP +65 83037290
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900256402
VEHICLE NO : **SMR 296 P**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/12/2019
ENGINE NO : CHZ C35258
CHASSIS NO : WAUZZZ8V0LA002554
MILEAGE : 12416KM
DATE IN : 2-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Oct-20
PLACE OF ACCIDENT : DECATHLON BEDOK CARPARK D

16 days

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 296 P**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$ 1,800.00 ?	
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00 ?	
3	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00 ✓	
4	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 ✓	
5	TO RENEW REAR WINDSCREEN AND BOTH REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 900.00 ✓	
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND BOTH REAR 1/4 GLASS.	S/N \$ 400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 4,460.00	


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 296 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	150
8	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	✓
9	TO DISLodge AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✓
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD BOTH REAR FENDERS, LHS SILL PANEL AND REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 10,000.00	7500
11	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, RHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, RHS SILL PANEL, ROOF CHANNELS, DRAIN PANELS, LHS B PILLAR, END PANELLING, REAR LID HINGES AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 7,800.00	5500
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 25,452.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR WINDSCREEN		\$ 805.00	rec ✓
3 PRIMER		\$ 19.00	rec ✓
4 REAR FENDER - RH		\$ 2,305.00	rec ✓
5 SIDE WINDOW - RH		\$ 563.00	rec ✓
6 REAR BUMPER		\$ 1,944.00	rec ✓
7 REAR BUMPER FIXING PARTS		\$ 191.00	x an
8 REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	ib RH DMG
9 REAR BUMPER LOCKING MECHANISM	2	\$ 59.00	?
10 REAR BUMPER SPOILER		\$ 234.00	DE ✓
11 REAR LIGHT REFLECTOR - LH / RH	2	\$ 82.00	41 RH CRACKED
12 LED TAIL LIGHT - LH / RH	2	\$ 1,734.00	867 RH OUT
13 TAIL LIGHT TRIM - LH / RH	2	\$ 60.00	30 RH OUT
14 REAR BUMPER BRACKET - LH		\$ 27.00	?
15 REAR BUMPER BRACKET - RH		\$ 28.00	?
16 REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 132.00	66 RH CRACKED
17 REAR PARKING AID SENSOR - INNER / OUTER	4	\$ 968.00	1 piece damaged 242
18 REAR PARKING AID SEAL RING	4	\$ 14.00	rec ✓
19 REAR BUMPER WIRING SET		\$ 510.00	x an
20 REAR CROSS PANEL		\$ 356.00	DD ✓
SUB TOTAL SPARE PARTS	:	\$ 10,063.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR CROSS PANEL REINFORCEMENT		\$ 725.00	mg ✓
22 REAR LID		\$ 2,564.00	mg ✓
23 REAR LID ATTACHMENT PARTS		\$ 291.00	xnn
24 REAR LID HINGE - LH / RH	2	\$ 506.00	?
25 REAR LID FLAP GASKET		\$ 203.00	xnn
26 REAR LID LOCK STRIKER		\$ 49.00	xnn
27 REAR LID LOCK		\$ 184.00	xnn
28 PACKING ADHESIVE		\$ 18.00	rec ✓
29 REAR LID LOCK ACTUATOR		\$ 1,330.00	xnn
30 AUDI EMBLEM		\$ 122.00	rec ✓
31 A3 INSCRIPTION		\$ 95.00	rec ✓
32 REAR LID TRIM PANEL		\$ 303.00	xnn
33 REAR CROSS PANEL TRIM		\$ 153.00	?
34 REAR NO PLATE	S/N	\$ 60.00	xnn
35 REAR WINDSCREEN SEALANT	S/N	\$ 200.00	rec ✓
36 1/4 GLASS SELANT	S/N	\$ 200.00	rec ✓
37 METAL FILLER POWDER	S/N	\$ 280.00	rec ✓
38 STONE CHIP	S/N	\$ 180.00	rec ✓
39 CAVITY WAX	S/N	\$ 140.00	rec ✓
40 ACRYLIC SEALANT	S/N	\$ 180.00	rec ✓
41 SUNDRIES		\$ 500.00	?,
TOTAL SPARE PARTS	:	\$ 18,346.00	
TOTAL LABOUR CHARGES	:	\$ 25,452.00	
GRAND TOTAL	:	\$ 43,798.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT