




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|---------------------------------|------------|---|
| INDIA INTERNATIONAL INSURANCE PL | | Ref : CS3/III20008356/R1vd3e2-1 | | |
| 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | Date : 12-11-2020 | |  |
| | | Code : III2 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHC 3372X | Veh. Inspected | SMJ 6539S | |
| Policy No. | MCOM0015 | Coverage (\$) | 0.00 | |
| Claim No. | MCT20080067 | Excess (\$) | 0.00 | |
| Assign From | CARINE KHEK | Assign Date | 16/10/2020 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | B.M.W. M5 | c.c | 4395 | |
| Engine No. | HIDDEN | Year of Reg. | 2013 | |
| Chassis No. | WBSFV92040DX96069 | Colour | BLACK | |
| Odometer | 78619 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 265/35Z R20 | MICHELIN | 6 mm | |
| L/H Front Tyre | 265/35Z R20 | MICHELIN | 6 mm | |
| R/H Rear Tyre | 265/35Z R20 | MICHELIN | 6 mm | |
| L/H Rear Tyre | 265/35Z R20 | MICHELIN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 04/08/2020 | Inspection Date | 13/08/2020 | |
| Survey held at | B'S PERFORMANCE PTE LTD 7 SOON LEE STREET ISPACE #01-38 SINGAPORE 627668 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | | |