

Enquire Vehicle Owner Details

Enquire Vehicle Owner Details (As At 04 Aug 2020 / 17:50:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

199303821R

Owner Name:

COMFORT TRANSPORTATION PTE LTD

Registered Address Type:

Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:

383

Registered Street Name:

SIN MING DRIVE

Registered Unit No.:

-

Registered Building Name:

GAS BUILDING

Registered Postal Code:

575717

Vehicle Insurance Details

Vehicle No.:

SHC3372X

Make Description/Model:

HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name:

INDIA INT'L INS PTE LTD

Save as PDF

OK →

Print



B's Performance Pte Ltd

Biz Reg No. : 201437139W

No.7 Soon Lee Street #01-38 iSpace Singapore 627608

Tel & Fax : 6397 5920 Email : bsperformancepteltd@gmail.com

24 hours Towing Service : 8699 1616

GST Reg No. : 201437139W

Tax Invoice

Bill To : India International Insurance Pte Ltd

Address :

Tel :

Inv. No. : BS2009-1019

Inv. Date : 10/09/2020

Ref No. : 5-Aug

Vehicle No : SMJ 6539 S

Model : BMW M5

Mileage : 117666 KM

Terms : C.O.D

No.	Description	Quantity	Unit Price	Amount
1	Accident Towing		\$	180.00

** All cheque should be crossed and made payable to

" B's Performance Pte Ltd " . No Official receipt will be issued.

For Bank Transfer: OCBC Current Account No **6892 4700 5001**

For Paynow payment, Pls pay via Paynow UEN number: **201437139W**

Pls indicate invoice no under "**UEN/Bill Reference Number**".

** If no remark is made within 10 days, this invoice will be considered as correct.

Sub Total : \$ **180.00**

Gst 7% : \$ **12.60**

Total : \$ 192.60

😊 Thank you for your business 😊

Should you have any enquiries concerning this invoice
Please Contact : 6397 5920



B's Performance Pte Ltd



Bee Car Leasing Svc Pte Ltd

No. 7 Soon Lee Street #01-38 iSpace Singapore 627608

Tel : (65) 6397 5920 / (65) 9776 9209

Email : beecarleasing@gmail.com

INVOICE

Bill To : Liberty Insurance Pte Ltd

Address :

Tel :

Inv. No. : BC2009-0209

Date : 16/09/2020

Ref No. : 5-Aug

Veh No : SMJ 6539 S

Model : BMW M5

Mileage : 117666 KM

Terms : C.O.D

No.	Description	Quantity	Unit Price	Amount
1	Car Rental -SJZ4623X-BMW 523 Out :26-08-2020 In :15-09-2020	21 Days	\$	3,780.00



Total : \$ 3,780.00

**** All cheque should be crossed and made payable to " Bee Car Leasing Svc Pte Ltd" ****

This is computer generated document . No signature is required .

B'S PERFORMANCE PTE LTD

7 SOON LEE STREET #01-38 ISPACE, SINGAPORE 627608

TEL : 6397 5920 HP: 8699 1616

Email: bsperformancepteltd@gmail.com

GST Reg no : 201437139W

Owner: Watercare Products Pte Ltd

Date: 2-Sep-20

Address: C/o: B's Performance Pte Ltd
7 Soon Lee Street,
#01-38 Ispace, Singapore 627608

Date of accident: 04 August 2020

Final repair bill for SMJ 6539 S

Description	Amount (S\$)
Lump Sum Repair Costs	\$ 9,100.00
Plus 7% GST	\$ 637.00
	<u>\$ 9,737.00</u>

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Watercare Products Pte Ltd
C/o: B's Performance Pte Ltd
7 Soon Lee Street, #01-38
Ispace, Singapore 627608

Invoice No: CL/200429

Ref No: BS/08/2002/TP

Date: 2 September 2020

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SMJ 6539 S</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 681.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Watercare Products Pte Ltd
C/o: B's Performance Pte Ltd
7 Soon Lee Street, #01-38
Ispace, Singapore 627608

Date : 2 September 2020
Our ref : BS/08/2002/TP

Accident Date : 04 August 2020
Inspection Date : 13 August 2020
Repairer Name : B's Performance Pte Ltd
7 Soon Lee Street, #01-38
Ispace, Singapore 627608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SMJ 6539 S
Make / Model : BMW M5
Chassis No : WBSFV92040DX96069
Engine No : 22790346S63B44B

Year / Capacity : 2013 / 4395 cc
Colour : Black
Mileage : 78619

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Michelin	265/35 R20	5 mm	Sport
Front Offside	: Michelin	265/35 R20	5 mm	Sport
Rear Nearside	: Michelin	265/35 R20	5 mm	Sport
Rear Offside	: Michelin	265/35 R20	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **61** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 9,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: SMJ 6539 S

Our Ref No: BS/08/2002/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front n/s headlamp assy	Damage	\$ 2,600.00	\$ 2,600.00
1	Front bumper	Damage	\$ 1,500.00	\$ 1,500.00
1	Front bumper n/s side retainer	Necessary	\$ 135.00	\$ 135.00
1	Front bumper n/s side view camera	Damage	\$ 495.00	\$ 495.00
1	Front n/s fender	Repair	\$ 1,151.00	
1	Front n/s wheel hub with bearing	Damage	\$ 501.00	\$ 501.00
1	Front n/s shock absorber	Damage	\$ 871.00	\$ 871.00
1	Front n/s knuckle arm	Damage	\$ 691.00	\$ 691.00
1	Front n/s lower arm	Damage	\$ 501.00	\$ 501.00
1	Front n/s control arm	Damage	\$ 495.00	\$ 495.00
			\$ 8,940.00	\$ 7,789.00
		Less 5%	\$ 447.00	\$ 389.45
	Total Cost - List Items		\$ 8,493.00	\$ 7,399.55

SPECIAL NETT ITEMS

1	Front n/s tyre (Depreciation)	Damage	\$ 600.00	\$ 300.00
1	Front n/s sport rim	Damage	\$ 2,200.00	\$ 2,200.00
	Total Cost - Special Nett items		\$ 2,800.00	\$ 2,500.00

Total cost of parts
\$ 11,293.00 \$ 9,899.55

Vehicle Registration No: SMJ 6539 S

Our Ref No: BS/08/2002/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 11,293.00	\$ 9,899.55

LABOUR

1	To check wiring , lighting and resetting headlamps focussing.	\$ 80.00	\$ 50.00
2	To remove and refit front sensor.	\$ 120.00	\$ 80.00
3	To remove and refit front undercarriage.	\$ 350.00	\$ 300.00
4	To conduct wheel alignment.	\$ 150.00	\$ 120.00
5	To apply undercoating on repaired and replaced panel.	\$ 80.00	\$ 30.00
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 850.00	\$ 500.00
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 800.00	\$ 440.00

GRAND TOTAL
\$ 13,723.00 \$ 11,419.55

Vehicle Registration No: SMJ 6539 S

Our Ref No: BS/08/2002/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 9,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser









