

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP19090021

Date: 29 NOV 2019

AKA ZEN

c/o D's Graffiti Concepts Pte Ltd
Blk 1, #01- 59
Kaki Bukit Ave 6
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 04 Sept 2019

Workshop Name and Address

D's Graffiti Concepts Pte Ltd
Blk 1, #01- 59
Kaki Bukit Ave 6
Singapore 417883

As per your instruction dated 05 Sept 2019
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SKV7333Y

1. VEHICLE PARTICULARS

Registration No : SKV7333Y
Model : TOYOTA COROLLA ALTIS
Year / Capacity : Apr 2007 / 1598 cc
Chassis No : MR053ZEC107142321

Engine No : 3ZZ4633826
Mileage : 300 408 km
Colour : Meatlic black

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front & rear side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 12 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKV7333Y

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front bumper ✓	bent	\$ 638.10	\$ 485 638.10 ✓
2 pcs	Front bumper side retainer ✓	bent	\$ 45.00	\$ 35 45.00 ✓
2 pcs	Front bumper bracket X SVC	distorted	\$ 78.20	\$ 78.20 X
1 pc	Front bumper reinforcement ✓	necessary	\$ 418.50	\$ 343 418.50 ✓
10 pcs	Front bumper clips ✓	necessary	\$ 50.00	\$ 50.00 ✓
2 pcs	Headlamp assembly LH ✓ CRA / RH X SVC	cracked	\$ 684.00	\$ 342 684.00 ✓
1 pc	Bonnet ✓	bent	\$ 590.20	\$ 590.20 ✓
1 pc	Bonnet lock ✓	distorted	\$ 85.00	\$ 85.00 ✓
1 pc	Front grille ✓	cracked	\$ 258.40	\$ 258.40 ✓
1 pc	Front grille badge ✓	damaged	\$ 55.00	\$ 55.00 ✓
6 pcs	Front grille clips ✓	necessary	\$ 56.00	\$ 30 56.00 ✓
1 pc	Front support panel X Repair	bent	\$ 650.00	\$ 650.00 X
1 pc	Air cond condensor X SVC	damaged	\$ 729.40	\$ 729.40 X
1 pc	Radiator assembly X SVC	damaged	\$ 1,507.40	\$ 1,507.40 X
1 pc	Rear bumper ✓	bent	\$ 525.70	\$ 525.70 ✓
2 pcs	Rear bumper side retainer ✓	bent	\$ 87.40	\$ 57 87.40 ✓
2 pcs	Rear bumper side attachment X SVC	bent	\$ 87.80	\$ 87.80 X
2 pcs	Rear bumper stay ✓	bent	\$ 87.10	\$ 87.10 ✓
10 pcs	Rear bumper clips ✓	necessary	\$ 90.00	\$ 30 90.00 ✓
1 pc	Bootlid ✓	bent	\$ 798.90	\$ 649.15 798.90 ✓
1 pc	Bootlid lock ✓	distorted	\$ 101.80	\$ 101.80 ✓
2 pcs	Bootlid reflector ✓	damaged	\$ 653.60	\$ 570 653.60 ✓
2 pcs	Bootlid reflector sealant X SVC	necessary	\$ 100.00	\$ 100.00 X
4 pcs	Bootlid reflector clips X SVC	necessary	\$ 51.60	\$ 51.60 X
1 pc	Bootlid weatherstrip ✓	deformed	\$ 105.80	\$ 105.80 ✓
1 pc	Bootlid emblem '1.6E' ✓	necessary	\$ 32.50	\$ 32.50 ✓
1 pc	Bootlid emblem 'VTI' ✓	necessary	\$ 45.50	\$ 45.50 ✓
1 pc	Bootlid emblem 'Corolla' ✓	necessary	\$ 38.50	\$ 38.50 ✓
1 pc	Bootlid emblem 'Altis' ✓	necessary	\$ 34.50	\$ 34.50 ✓
1 pc	Bootlid chrome X SVC	necessary	\$ 328.70	\$ 328.70 X
4 pcs	Bootlid chrome clips X SVC	necessary	\$ 51.60	\$ 51.60 X
2 pcs	Taillamp ✓	cracked	\$ 737.80	\$ 640 737.80 ✓
2 pcs	Taillamp sealant X SVC	deformed	\$ 150.00	\$ 150.00 X
4 pcs	Taillamp clips X SVC	necessary	\$ 51.60	\$ 51.60 X
2 pcs	Taillamp lower panel X SVC	distorted	\$ 191.80	\$ 191.80 X
8 pcs	Taillamp lower panel rivets X SVC	necessary	\$ 103.20	\$ 103.20 X
2 pcs	Taillamp base panel X SVC	distorted	\$ 283.60	\$ 283.60 X
1 pc	Rear end panel ✓	bent	\$ 781.25	\$ 655 781.25 ✓
1 pc	Rear end panel top trim ✓	bent	\$ 372.25	\$ 179.28 372.25 ✓
4 pcs	Rear end panel top trim clips ✓	necessary	\$ 51.60	\$ 20 51.60 ✓
1 pc	Rear floor panel	distorted - repair	\$ 987.25	\$ -
1 pc	Rear floor panel insulator clutch X SVC	deformed	\$ 374.40	\$ 374.40 X
Parts Sub-Total			\$ 13,150.95	\$ 6097.03 12,163.70
Discount 25.00%			\$ 3,287.74	\$ 3,040.93
			\$ 9,863.21	\$ 4572.77 9,122.78

Vehicle Number : SKV7333Y

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
2 pcs	Number plate casing ✓	bent	\$ 120.00	\$ 40 120.00
2 pcs	number plate ✓	damaged	\$ 80.00	\$ 20 80.00
1 set	Reverse sensor ✓	shocked	\$ 280.00	\$ 200 250.00
Special Nett Sub-Total			\$ 480.00	\$ 260 450.00
Spare Parts Total			\$ 10,343.21	\$ 9,572.78

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f \$	10,343.21 \$	9,572.78
1	Towing	\$ 120.00	\$ X 120.00
2	To check and reconnect snap wiring	\$ 180.00	\$ 30 150.00
3	To tuff coat affected areas	\$ 180.00	\$ 60 150.00
4	To remove and replace interior upholstery	\$ 180.00	\$ 60 150.00
5	To remove and replace air cond condensor, piping vacuum and top up gas	\$ 180.00	\$ 60 150.00
6	To remove and replace radiator, hoses, fan and top up coolant	\$ 180.00	\$ 60 150.00
7	To respray affected areas	\$ 1,800.00	\$ 1400 1,600.00
8	To renew damaged parts, straighten and repair front & rear chassis member, front & rear fender inner panel and aligned all parts.	\$ 2,000.00	\$ 1000 1,800.00
9	To remove and replace reverse sensor	\$ 180.00	\$ 40 150.00
10	To remove and transfer boot lid mechanism	\$ 200.00	\$ 40 180.00
	Total \$	15,543.21 \$	2750 14,172.78

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 12,050.00

7582.77

-20%: 6050

8 days

Fong Kok Heng

Fong Kok Heng
Qualified Appraiser

