



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 531928891

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

O/D

(3rd Party Claim Against GTI

)

Repair Estimate

Vehicle No. : SUH8096L

Make & Model : TOYOTA PRIUS 1.8 hybrid

Submitted by : Ben

COE Expiry : 17.11.2026

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01a	Exhaust air garnish / BL	01	\$145.00		
01	Front bumper / RE	01	\$1,779.00		
02	Front top grille / RE	01	\$549.00		
03	Lower front grille / RE	01	\$342.00		
04	Toyota emblem / AT	01	\$85.00		
05	Engine top garnish / RE	01	\$290.00		
06	Front bonnet / Bus	01	\$1,100.00		
07	Front reinforcement bar / BT (Upper)	01	\$420.00		
08	Radiator / BT	01	\$495.00		
09	Cooling coil / BT	01	\$399.00		
10	Radiator fans x 2	01	\$120.00		
11	Radiator casing	01	\$320.00		
12	End panel / BT	01	\$595.00		
13	Anti-crash sensor	01		check price	
Special note					
01	Clips / retainers @ \$60 / pct / RE	01	\$60.00		
02	Licence plate & casing / BT	01	\$52.00		
Labour description					
01	Disassemble / Assembly of all affected parts including panel knocking & welding of chassis support, end panel, fenders x 2	01	\$1400.00	600	
02	Spray painting of all affected parts including anti-rust paint, washed after polish	01	\$1000.00	600	
03	Reset / clearing of anti-collision error & etc	01	\$400.00	120	
Supplementary					

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

- ① Air Filter / CFA
- ② Front Bumper Rubber / CFA
- ③ Front Reinforcement lower / BT
- ④ Air Duct lower / CFA



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

O/D
(3rd Party Claim Against CTI)

Repair Estimate

Vehicle No. : SLH8096L
Make & Model : Toyota Prius 1.8 hybrid

Submitted by : Ben
COE Expiry : 17.11.2026

S/No	Part Description	Qty	Price	Unit Price	Disposition by
	Supplementary				
05	Brace panel / BT.				
06	Lower Reinforcement Bracket / BT				
07	Front Bumper Sponge / CAA				
	Front Bumper Lower Cover / TR.				
	Head lamp X2 / BR				
	5 Days.				
	Excess \$ 2000				
	Not Authorised.				
	Part by part				
	before paint photos.				
	Gino Qiang 82880282				
	21/10/2020.				

Note: If any the quoted parts are recommended to be repaired, then no additional labour cost will be charged accordingly under supplementary.

UKK Auto Consultants hence notify

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

- Supplement (if items) must be resurveyed and is subject to final approval from Insurance Company

Acknow

Signature

Date: