

10260.4

-25%: 7695.3

1410

Total: 9105.3



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 639266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

O/D

(3rd Party Claim Against Cti

)

Repair Estimate

Vehicle No. : SUH8096L
 Make & Model : TOYOTA PRIUS 1.8 hybrid

Submitted by : Bm
 COE Expiry : 17.11.2026

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	Exhaust air gauge / Bt	01	\$140.00	120	
01	Front bumper / Bt	01	\$1,779.00	495.5	
02	Front top grille / Bt	01	\$549.00	189.7	
02	Lower front grille / Bt	01	\$342.00	281.85	
04	Toyota emblem / Bt	01	\$85.00	/	
05	Engine top cover / Bt	01	\$290.00	/	
06	Front bonnet / Bt	01	\$1,100.00	853.6	
07	Front reinforcement bar / Bt (Upper)	01	\$420.00	/	
08	Radiator / Bt	01	\$495.00	/	
09	Cooling oil / Bt	01	\$399.00	/	
10	Radiator fans x 2 / Bt	02	\$120.00	X	
11	Radiator casing / Bt	01	\$320.00	255.8	
12	End panel / Bt	01	\$595.00	381.45	
13	Anti-brush sensor / Bt	01	1400	400 ✓	
	Special net				
01	Wsp / retainers / Bt	01	\$460.00	50	
02	License plate & lamp / Bt	01	\$450.00	40	
	Labour description				
01	Removal / Assembly of all affected parts including panel knocking & welding of chassis support, end panel, fenders x 2	01	\$1400.00	600	
02	Spray painting of all affected parts including anti-rust paint, washed after polish	01	\$1000.00	600	
03	Reset / learning of anti-collision error & etc	01	\$400.00	120	
	Supplementary				

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

- ① Air Filter / CFA
- ② Front bumper rubber / CFA
- ③ Front Reinforcement lower - Bt
- ④ Air Duct lower / CFA

\$360 258
 \$42 /
 \$230 /
 \$90 /

5. Air Guide ✓ DE \$85 ✓

ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 639268

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

01D
(3rd Party Claim Against CTi

9595.4
- 25% 7196.55
1410
8606.55

Repair Estimate

Vehicle No. : SH8096L
Make & Model : Toyota Prius 1.8 Hybrid

Submitted by : Ben
COE Expiry : 17.11.2028

S/No	Part Description	Qty	Price	Unit Price	Disposition by
	Supplementary				
05	Brake panel / BT	01	\$69.00	/	
06	Lower Relacement Bracket	01 BT	\$150.00	01 BT	BT
07	Int Bumper Sponge / CRA	01	\$85.00	/	
08	Int Bumper Lower Cover / CRA	01	\$220.00	120	
09	Head lamp X2 / BR	01+01	\$2500.00	1825	
10	Air resonator / CRA	01	\$45.00	/	
11	Toyota circuit Emblem (T) * DM	01	\$580.00	* DM	DM
12	Oil cooler / BT	01	\$260.00	/	
	5 Days.				
	Excess \$2000				
	Not Authorised.				
	Part by part				
	before paint photos.				
	Emo Qiang 8288082				
	21/10/2020.				

Work Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis

these are additional labour cost will be charged

- Supplemental items must be resurveyed and is subject to approval from Insurance Company

Action:
Signature:
Date:

Note: If any the quoted parts are recommended to be repaired accordingly under supplementary.

B. RH returner - \$55.00 / BT
14. Radiator top bracket - \$59.00 / BT
15. Radiator lower plate - \$165.00 X NM
16. License plate near plate - \$69.00 / BT
17. Bumper back base - \$290.00 / BT
18. Radiator Motor x2 - \$650.00 / NM
19. Radiator lower base bkt - \$280.00 / BT
120