



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteitd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 14/10/2020
TP Veh Reg No: SLH1931Y

Estimate No: ES2000090
Date: 16 Oct 2020
Policy No:
Veh Reg No: SKC1554R
Make/Model: VOLVO XC60 T5 2.0 AT
ABS D/AB 2WD 5DR
TURBO
Chassis No: YV1DZ475BB2223931
Engine No: B4204T71025073
Reg. Date: 26/07/2011

Not Authorized

*11 Pny @ 2850h
Presumy After Paint*

4 days

Estimate Repair Cost to Vehicle No :SKC1554R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUZZER SENSOR	332.50	1 PC	<i>Sm</i> 332.50	<i>X</i>
2 REVERSE SENSOR CORNER - LH	465.00	1 PC	<i>Sm</i> 465.00	<i>X</i>
3 REVERSE SENSOR CORNER - RH	465.00	1 PC	<i>Sm</i> 465.00	<i>X</i>
4 REVERSE SENSOR CENTRE - LH	465.00	1 PC	<i>Sm</i> 465.00	<i>X</i>
5 REVERSE SENSOR CENTRE - RH	465.00	1 PC	<i>Sm</i> 465.00	<i>X</i>
6 REAR REVERSE SENSOR WIRE	550.00	1 PC	<i>Sm</i> 550.00	<i>X</i>
			2,742.50	2,742.50
Spare Parts				
7 BOOT EMBLEM XC60	65.00	1 PC	<i>Me</i> 65.00	<i>—</i>
8 BOOT EMBLEM T6	92.50	1 PC	<i>Me</i> 92.50	<i>—</i>
9 BOOT EMBLEM 'VOLVO'	185.00	1 PC	<i>Me</i> 185.00	<i>—</i>
10 REAR BUMPER	2,680.50	1 PC	<i>Bm</i> 2,680.50	<i>—</i>
11 REAR BUMPER REINFORCEMENT	904.50	1 PC	<i>R</i> 904.50	<i>X</i>
12 REAR BUMPER INNER GARNISH	320.20	1 PC	<i>Sm</i> 320.20	<i>X</i>
13 REAR BUMPER SIDE RETAINER - LH	95.20	1 PC	<i>R</i> 95.20	<i>X</i>
14 REAR BUMPER SIDE RETAINER - RH	95.20	1 PC	<i>Sm</i> 95.20	<i>X</i>
15 REAR BUMPER TOWING COVER	45.00	1 PC	<i>Sm</i> 45.00	<i>X</i>
16 REAR END PANEL	1,310.50	1 PC	<i>R</i> 1,310.50	<i>X</i>
17 REAR END PANEL GARNISH	440.00	1 PC	<i>Sm</i> 440.00	<i>X</i>
18 REAR EXHAUST BOX	1,925.10	1 PC	<i>R</i> 1,925.10	<i>X</i>
19 REAR EXHAUST MOUNTING	160.00	1 PC	<i>Sm</i> 160.00	<i>X</i>
20 REAR BUMPER SPONGE	385.50	1 PC	<i>Sm</i> 385.50	<i>X</i>
21 REAR BUMPER CHROME GARNISH (TOP)	335.90	1 PC	<i>CM</i> 335.90	<i>—</i>
22 REAR BUMPER LOWER SPOILER	565.20	1 PC	<i>Red</i> 565.20	<i>—</i>
23 REAR BUMPER LOWER SPOILER REFLECTOR - LH	420.85	1 PC	<i>Sm</i> 420.85	<i>X</i>
24 REAR BUMPER LOWER SPOILER REFLECTOR - RH	420.85	1 PC	<i>Sm</i> 420.85	<i>X</i>
			10,447.00	10,447.00
Labour				
25 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	<i>500</i>
26 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	<i>500</i>
27 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	<i>nn</i> 120.00	<i>X</i>
28 TO COMPUTER RESET.	380.00	1 JOB	<i>nn</i> 380.00	<i>X</i>



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 14/10/2020
TP Veh Reg No: SLH1931Y

Estimate No: ES2000090
Date: 16 Oct 2020
Policy No:
Veh Reg No: SKC1554R
Make/Model: VOLVO XC60 T5 2.0 AT
ABS D/AB 2WD 5DR
TURBO
Chassis No: YV1DZ475BB2223931
Engine No: B4204T71025073
Reg. Date: 26/07/2011

Estimate Repair Cost to Vehicle No :SKC1554R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
29 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	15/
			3,300.00	3,300.00
			Total	SS 16,489.50
			Add GST @ 7%	1,154.27
			Total Amount Payable	SS 17,643.77

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND SIX HUNDRED FORTY THREE AND CENTS SEVENTY SEVEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: