



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102430

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/04/2021
Reference CC6/CTI20011277/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 5995K
Insured Veh. GBG 7753D
Claim No. SNM20D203916/C02
Policy No. DMCVSNW00101882003
Accident Date 16/10/2020
Inspection Date 19/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI20011277/Upa3q2 Date: 12/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 7753D	Veh. Inspected	SLM 5995K	
Policy No.	DMCVSNW00101882003	Coverage (\$)	0.00	
Claim No.	SNM20D203916/C02	Excess (\$)	0.00	
Assign From		Assign Date	19/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZGE206033109	Colour	WHITE	
Odometer	294274 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BFGOODRICH	6 mm	
L/H Front Tyre	195/65 R15	BFGOODRICH	6 mm	
R/H Rear Tyre	195/65 R15	BFGOODRICH	6 mm	
L/H Rear Tyre	195/65 R15	BFGOODRICH	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/10/2020	Inspection Date	19/10/2020	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 5995K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	210.45	181.10
1	REAR TAILGATE	BADLY DENTED	1,410.35	1,410.35
2	REAR TAILGATE HINGE RH/LH @\$68.10	NOT NECESSARY	136.20	-
2	REAR TAILGATE DAMPER RH/LH @\$210.90	NOT NECESSARY	421.82	-
1	REAR TAILGATE RUBBER	TWISTED	395.10	395.10
1	REAR TAILGATE LOCK	DENTED / SHORTED	359.42	359.42
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	40.50	-
1	REAR TAILGATE KEYLESS SMART	CRACKED	292.10	292.10
1	REAR TAILGATE INNER TRIM	DEFORMED / TWISTED	591.45	591.45
1	REAR TAILGATE WIPER MOTOR	BENT / JAMMED	590.10	590.10
1	REAR TAILGATE OPENING CONTROL SWITCH	SHORTED	176.50	176.50
2	REAR TAILGATE NUMBER PLATE LAMP @\$69.10	NOT NECESSARY	138.20	-
1	REAR TAILGATE CHROME MOULDING	BENT / CRACKED	393.10	393.10
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	74.10	74.10
1	REAR TAILGATE EMBLEM VALVE MATK	NECESSARY	80.50	80.50
2	REAR TAILGATE REFLECTOR RH/LH @\$395.99	SCRATCHED	791.98	791.98
1	REAR TAILLAMP RH	NOT NECESSARY	401.20	-
1	REAR BUMPER	DENTED / DEFORMED	697.40	697.40
2	REAR BUMPER REFLECTOR RH/LH @\$69.66	NOT NECESSARY	139.32	-
2	REAR BUMPER HOLDER RH/LH @\$66.19	NOT NECESSARY	132.38	-
2	REAR BUMPER BRACKET RH/LH @\$68.55	NOT NECESSARY	137.10	-
2	REAR BUMPER SIDE RETAINER RH/LH @\$124.10	BENT	248.20	248.20
1	REAR END PANEL	BADLY DENTED	618.95	618.95
1	REAR END PANEL GARNISH	TWISTED	391.25	391.25
1	REAR FENDER INNER TRIM RH	NOT NECESSARY	708.10	-
	LESS 25% DISCOUNT		-2,393.94	-1,822.90
			7,181.83	5,468.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAILGATE STICKER 'KIM' (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	350.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
			815.00	345.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT ,CUT/WELD REAR PANEL AND REPLACE ACCIDENT PARTS.		900.00	680.00
	TO SPRAY PAINTING ON ACCIDENT PARTS.		1,200.00	950.00
	TO CHECK WIRING .		30.00	30.00
	TO REMOVE ,REFIX REAR WINDSCREEN .		120.00	120.00
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.00
	TO REMOVE ,REFIX CUSHION AND INNER TRIM .		120.00	80.00
	TO REFIX REAR CAMERA ,REPLACE REVERSE CAMERA AND REVERSE SENSOR .		150.00	50.00
	TO TUFF -KOTE.		90.00	60.00
			2,710.00	2,030.00
GRAND TOTAL			10,706.83	7,843.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,250.00

Report Ref No. CC6/CTI20011277/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5995K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5995K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5995K

RE-INSPECTION

