



# 新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981  
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

16 Oct 2020

## THIRD PARTY CLAIM

Third Party Vehicle No : SFF52Y

Date of Accident : 30/09/2020

## M/S LAM CHUAN IMPORT-EXPORT PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

## COST OF REPAIR TO TOYOTA DYNA : GBB 3055 M

A) Chassis No : JN1SC2F24Z0855412

B) Date of Registration : 27/11/2008

| S/No. | Pc/s | Item(s) :-                 |
|-------|------|----------------------------|
| 01.   | 1    | tailgate                   |
| 02.   | 1    | 'DYNA' sticker             |
| 03.   | 2    | tailgate lock @\$98.80     |
| 04.   | 1    | sidegate RH                |
| 05.   | 2    | tail lamp @\$220.00        |
| 06.   | 2    | tail lamp bracket @\$89.20 |

|          |                         |
|----------|-------------------------|
| \$       |                         |
| 1,255.80 | bt                      |
| 28.30    | net                     |
| 197.60   | TXR                     |
| 1,154.80 | R                       |
| 440.00   | 14-11-1, RH-? cut ✓     |
| 89.20    | 178.40 14-11-1, RH-? XR |

|                      |          |         |
|----------------------|----------|---------|
|                      | 3,254.90 | 1813.30 |
| Less 25% discount :- | 813.73   | 1359.97 |
|                      | 2,441.17 |         |

|     |   | Special Nett Item(s) :- |
|-----|---|-------------------------|
| 07. | 1 | reverse sensor          |
| 08. | 1 | rear deck               |
| 09. | 1 | rear canopy             |
| 10. | 1 | rear number plate       |
| 11. | 1 | '70 KmH' sticker        |
| 12. | 1 | '13 PAX' sticker        |

|          |          |
|----------|----------|
| 280.00   | 200nw    |
| 6,000.00 | RY SW500 |
| 2,800.00 | bn 1500. |
| 30.00    | bt       |
| 12.00    | net      |
| 12.00    | net      |
| 9,134.00 | 2254     |

### Labour Charges :

- a) To dismantle all damaged parts, panel beat / straighten ,all dents, check, adjust, replace and re-align the above parts
- b) To putty and spray paint tailgate in & out, rear deck, side gate RH and all affected portions
- c) To anti-rust rear affected portions

|          |      |
|----------|------|
| 1,000.00 | 600. |
| 1,000.00 | 600. |
| 150.00   | 40.  |

GST (7%) :-

|           |      |
|-----------|------|
| 13,725.17 | 1240 |
| 960.76    |      |

Total :-

|           |  |
|-----------|--|
| 14,685.93 |  |
| =====     |  |

1359.97

2254

1240

4853.97

I/s \$3900

7 days

Tan Min 97495749  
WP 19/10/20 @ 415pm  
Lump sum  
Resurvey after repair  
Tan Min 11 hands on  
07 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: