



# 新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981  
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

16 Oct 2020

## THIRD PARTY CLAIM

Third Party Vehicle No : SFF52Y

Date of Accident : 30/09/2020

## M/S LAM CHUAN IMPORT-EXPORT PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

## COST OF REPAIR TO TOYOTA DYNA : GBB 3055 M

A) Chassis No : JN1SC2F24Z0855412

B) Date of Registration : 27/11/2008

| S/No. | Pc/s | Item(s) :-                 |
|-------|------|----------------------------|
| 01.   | 1    | tailgate                   |
| 02.   | 1    | 'DYNA' sticker             |
| 03.   | 2    | tailgate lock @\$98.80     |
| 04.   | 1    | sidegate RH                |
| 05.   | 2    | tail lamp @\$220.00        |
| 06.   | 2    | tail lamp bracket @\$89.20 |

| \$                        |
|---------------------------|
| 1,255.80 <i>bt</i>        |
| 28.30 <i>bt</i>           |
| 197.60 <i>?</i>           |
| 1,154.80 <i>Rp</i>        |
| 440.00 <i>LH-LH, RH-?</i> |
| 178.40 <i>LH-LH, RH-?</i> |

3,254.90

Less 25% discount :-

813.73

2,441.17

| S/No. | Pc/s | Special Nett Item(s) :- |
|-------|------|-------------------------|
| 07.   | 1    | reverse sensor          |
| 08.   | 1    | rear deck               |
| 09.   | 1    | rear canopy             |
| 10.   | 1    | rear number plate       |
| 11.   | 1    | '70 KmH' sticker        |
| 12.   | 1    | '13 PAX' sticker        |

|                          |
|--------------------------|
| 280.00 <i>200mm</i>      |
| 6,000.00 <i>RY SW500</i> |
| 2,800.00 <i>bt 1500.</i> |
| 30.00 <i>bt</i>          |
| 12.00 <i>bt</i>          |
| 12.00 <i>bt</i>          |

9,134.00

### Labour Charges :

- To dismantle all damaged parts, panel beat / straighten ,all dents, check, adjust, replace and re-align the above parts
- To putty and spray paint tailgate in & out, rear deck, side gate RH and all affected portions
- To anti-rust rear affected portions

1,000.00 *600.*

1,000.00 *600.*

150.00 *40.*

13,725.17

GST (7%) :-

960.76

Total :-

14,685.93

=====

*Tan Min 97495749*  
*WP 19/10/20 @ 415pm*  
*Lump sum*  
*Resurvey after repair*  
*tailor 14 hours work*  
*07 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: