

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 17.10.20

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SMT6875T
MODEL : HONDA JAZZ
DATE OF ACCIDENT : 17.10.20
TIME OF ACCIDENT : 10:00HRS

Xiao Tony

JHM6K3850LS218015

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	CENTER PILLAR (OUTER) LH	1	\$ 1,149.60	\$ 1,149.60
2	CENTER PILLAR (INNER) LH	1	\$ 894.30	\$ 894.30
3	ROCKER PANEL(OUTER) LH	1	\$ 396.40	\$ 396.40
4	REAR DOOR LH Distorted	1	\$ 1,050.40	\$ 1,050.40
5	REAR DOOR OUTER MOULDING LH Not new	1	\$ 79.20	\$ 79.20
6	REAR DOOR CHECKER LH Not new	1	\$ 49.20	\$ 49.20
7	REAR DOOR HINGE LH	2	\$ 54.20	\$ 108.40
8	REAR DOOR INNER LOCK LH Dented	1	\$ 226.40	\$ 226.40
9	REAR DOOR LOCK CATCHER LH Not new	1	\$ 39.40	\$ 39.40
10	REAR DOOR LOWER WEATHERSTRIP LH Not new	1	\$ 79.40	\$ 79.40
11	REAR DOOR INNER TRIM LH Cracked	1	\$ 594.20	\$ 594.20
12	REAR DOOR POWER WINDOW MOTOR LH Not new	1	\$ 361.40	\$ 361.40
13	REAR DOOR REGULATOR GEAR LH Dented	1	\$ 231.40	\$ 231.40
14	REAR DOOR FRAME WEATHERSTRIP LH Not new	1	\$ 79.40	\$ 79.40
15	REAR DOOR SPEAKER LH Not new	1	\$ 96.20	\$ 96.20
16	REAR DOOR FRONT WEATHERSTRIP LH Not new	1	\$ 79.40	\$ 79.40
17	REAR DOOR GLASS CHANNEL LH Not new	1	\$ 59.20	\$ 59.20
18	REAR FENDER LH Dented	1	\$ 559.20	\$ 559.20
19	REAR FENDER INNER COWLING LH Not new	1	\$ 69.20	\$ 69.20
20	REAR FENDER AIR VENT LH Not new	1	\$ 49.20	\$ 49.20
21	REAR FENDER INNER PANEL LH Repairs	1	\$ 764.30	\$ 764.30
22	REAR WHEEL CAP LH Not new	1	\$ 175.20	\$ 175.20
23	REAR WHEEL RIM LH Not new	1	\$ 836.90	\$ 836.90
24	REAR ABS SENSOR Not new	1	\$ 209.40	\$ 209.40
25	REAR AXLE Not new	1	\$ 1,210.80	\$ 1,210.80
26	REAR SHOCK ABSORBER LH Not new	1	\$ 359.90	\$ 359.90
27	REAR WHEEL HUP C/W BEARING LH Dented	1	\$ 294.60	\$ 294.60
28	REAR BUMPER Repairs	1	\$ 592.40	\$ 592.40

+

+

+

✓

+

+

+

✓

+

+

+

✓

+

+

+

+

✓

+

+

+

+

+

+

+

✓

+

495

500 (SW)

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMT6875T
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 17.10.20
 TIME OF ACCIDENT : 10:00HRS

29	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.20	\$ 78.40	+
----	--------------------------------------	---	----------	----------	---

2857
2285-60

S.N: 500

TOTAL PRICE \$ 10,773.40
 LESS 20% \$ 2,154.68
 SUB TOTAL PRICE \$ 8,618.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	ROCKER PANEL(OUTER) SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	+
2	REAR DOOR INNER TRIM CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30. +
3	REAR DOOR GLASS SOLAR FILM LH <i>new</i>	1	\$ 480.00	\$ 480.00	+
4	REAR FENDER SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	+
5	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER UPPER TRIM (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR FENDER QUARTER GLASS SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	40. +
9	REAR FENDER QUARTER GLASS INNER SHIELD LH <i>new</i>	1	\$ 60.00	\$ 60.00	+
10	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	REAR WHEEL TYRE LH <i>new</i>	1	\$ 350.00	\$ 350.00	+
12	BRAKE OIL <i>Not new</i>	1	\$ 40.00	\$ 40.00	+

70

TOTAL \$ 1,710.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>+</i>
7	TRANSFER REAR DOOR MECHANISM LH	\$ 80.00	<i>✓</i>
8	REMOVE & REINSTALL REAR WINDOW GLASS LH	\$ 80.00	<i>60</i>
9	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	<i>+</i>

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMT6875T**
 MODEL : **HONDA JAZZ**
 DATE OF ACCIDENT : 17.10.20
 TIME OF ACCIDENT : 10:00HRS

10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	100
11	TO PRESS REAR WHEEL HUB BEARING	\$ 80.00	X
12	FOUR WHEEL ALIGNMENT	\$ 120.00	80.
13	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 200.00	60.
14	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	✓
15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	X.
16	RESET ABS LIGHT	\$ 350.00	X
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 6,320.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,328.72
 TOTAL LABOUR COST : \$ 6,320.00
 TOTAL REPAIR COST : \$ 16,648.72

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Li
 w/s 19/10/20.
 06 Days.

total: 4965.60
 w/s: 3.9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: