

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
Premier@Kaki Bukit S(415875)
Tel : 6789 5155 Fax : 6783 5155

TO	: BUDGET DIRECT	DATE	: 17-Oct-20
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SKZ9198L
ADDRESS	:	MODEL / MAKE	: HONDA VEZEL
TEL. NO.	:	CHASSIS NO.	: RU11107920
OWNER INSUANCE	: NTUC	ACCIDENT DETAIL	
POLICY NO.	: 51147966669	DATE	: 16-Oct-20
		TIME	: 13:40hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILLAMP LH <i>see in</i>	1	\$ 552.30	\$ 552.30
2	REAR BUMPER CENTER <i>let</i>	1	\$ 762.70	\$ 762.70
3	REAR BUMPER SIDE LH <i>let</i>	1	\$ 195.80	\$ 195.80
4	REAR BUMPER SIDE RETAINER LH/RH <i>24 mm</i>	2	\$ 16.40	\$ 32.80
5	REAR BUMPER REFLECTOR LH <i>see in</i>	1	\$ 151.40	\$ 151.40
6	REAR END PANEL <i>see in</i>	1	\$ 480.30	\$ 480.30
7	REAR FENDER ARCH GARNISH LH <i>see in</i>	1	\$ 192.80	\$ 192.80
8	REAR FENDER INNER AIR VENT LH <i>3x16.40</i>	1	\$ 33.10	\$ 33.10
9	REAR FENDER INNER SHIELD LH	1	\$ 198.10	\$ 198.10
TOTAL PRICE				\$ 2,599.30
LESS -20%				\$ (519.86)
SUB TOTAL PRICE				\$ 2,079.44

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILLAMP CLIPS SET LH <i>see in</i>	1	\$ 40.00	\$ 40.00
2	REAR BUMPER CENTER CLIPS SET <i>see in</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER LOWER LIP <i>let</i>	1	\$ 580.00	\$ 580.00
4	REAR BUMPER REVERSE SENSOR SET <i>see in</i>	1	\$ 280.00	\$ 280.00
5	REAR BUMPER TOP CHROME PAD <i>see in</i>	1	\$ 350.00	\$ 350.00
6	REAR END PANEL SEALANT <i>see in</i>	1	\$ 100.00	\$ 100.00
7	REAR FENDER ARCH GARNISH CLIPS SET LH <i>see in</i>	1	\$ 50.00	\$ 50.00
8	REAR FENDER INNER SHIELD CLIPS SET LH <i>see in</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 1,520.00

610

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 400.00	200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 400.00	200	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	40	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	x	

TOTAL \$ 1,040.00

470

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,599.44
 TOTAL LABOUR COST : \$ 1,040.00
 TOTAL REPAIR COST : \$ 4,639.44

Adrian L
 4/5 19/10/20
 020yr -

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

FAX NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

total: 1859.52
 4/5: 1450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: