



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN WEI YAN (CHEN WEIYAN)
	Reg No/Reg Date	SMH8475P / 12/02/201
	Date In/Mileage	/ 11441
	Chassis No	MMBSTA13AKH001119
	Engine No	3A92UHN8556
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 11:58	QUD	247 / DonBong	58606

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, REPAIR LH FRONT DOOR, REPAIR FRONT BOTH CHASSIS			✓	1800. 2700.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK			✓	100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM			✓	80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTION			✓	2450 2800.00
M SUNDRY * RE-APPLY BODY KITS SEALANT			✓	60? 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			✓	30.00 ✓
M SUNDRY APPLY BODY SEALANT			80	120.00 ✓
E PNT88000 REMOVE AND TRANSFER RH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL			120.	150.00 ✓
M SUNDRY PERFORM RUST PREVENTION			40	80.00 ✓
M SUNDRY APPLY LTA FOR APPLICATION BREAK SEAL AND RESEAL OPC FRONT NUMBER PLATE			✓	80.00 ✓
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME			bt	50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			✓	120.00 ✓
M SUNDRY			20.	50.00 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN WEI YAN (CHEN WEIYAN)
	Reg No/Reg Date	SMH8475P / 12/02/201
	Date In/Mileage	/ 11441
	Chassis No	MMBSTA13AKH001119
	Engine No	3A92UHN8556
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 11:58	QUD	247 / DonBong	58606

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUNDRIES				
M PANEL ASSY,FR END	1.00	1055.00	23.00	812.35
M PANEL,HEADLAMP SUPPORT,UPR	1.00	65.00	23.00	50.05
M CONDENSER ASSY,A/C REFRIGE	1.00	758.00	23.00	583.66
M PANEL,AIR GUIDE	1.00	112.00	23.00	86.24
M RADIATOR ASSY	1.00	967.00	23.00	744.59
M TANK ASSY,RADIATOR COND	1.00	42.00	23.00	32.34
M FAN,COOLING,LH	1.00	77.00	23.00	59.29
M SHROUD,COOLING FAN	1.00	130.00	23.00	100.10
M MOTOR,COOLING FAN	1.00	479.00	23.00	368.83
M LLC 4L	1.00	26.00	23.00	20.02
M PANEL,AIR GUIDE,RH	1.00	11.00	23.00	8.47
M PANEL,AIR GUIDE,LH	1.00	11.00	23.00	8.47
M HEADLAMP ASSY,LH	1.00	660.00	23.00	508.20
M HEADLAMP ASSY,RH	1.00	660.00	23.00	508.20
M LAMP ASSY,FOG,FR LH	1.00	303.00	23.00	233.31
M LAMP ASSY,FOG,FR RH	1.00	303.00	23.00	233.31
M HINGE,HOOD,LH	1.00	56.00	23.00	43.12
M HINGE,HOOD,RH	1.00	56.00	23.00	43.12
M HOOD	1.00	734.00	23.00	565.18
M INSULATOR,HOOD	1.00	177.00	23.00	136.29
M CLIP,HOOD INSULATOR	6.00	3.00	23.00	13.86
M LATCH,HOOD	1.00	69.00	23.00	53.13
M FENDER,FR LH	1.00	497.00	23.00	382.69
M FENDER,FR RH	1.00	497.00	23.00	382.69
M EMBLEM ECO	2.00	17.00	00.00	34.00
M PANEL ASSY,FR DOOR,RH	1.00	996.00	23.00	766.92
M TAPE,FR DOOR SASH,RH	1.00	29.00	23.00	22.33
M GARNISH,FR PILLAR,LH	1.00	30.00	23.00	23.10
M GARNISH,FR PILLAR,RH	1.00	30.00	23.00	23.10
M GRILLE,RADIATOR	1.00	554.00	23.00	426.58
M GRILLE,RADIATOR	1.00	554.00	23.00	426.58
M BRACKET,FR BUMPER,LH	1.00	13.00	23.00	10.01

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repairs.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

To Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN WEI YAN (CHEN WEIYAN)
	Reg No/Reg Date	SMH8475P / 12/02/201
	Date In/Mileage	/ 11441
	Chassis No	MMBSTA13AKH001119
	Engine No	3A92UHN8556
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 11:58	QUD	247 / DonBong	58606
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET,FR BUMPER,RH		1.00	13.00	23.00	10.01
M GRILLE,FR UNDER		1.00	165.00	23.00	127.05
M GARNISH,FR BUMPER,LH		1.00	127.00	23.00	97.79
M GARNISH,FR BUMPER,RH		1.00	127.00	23.00	97.79
M AIR DAM,SIDE,FR LH		1.00	18.00	23.00	13.86
M AIR DAM,SIDE,FR RH		1.00	18.00	23.00	13.86
M COVER,HEADLAMP SUPT PANEL		1.00	62.00	23.00	47.74
M CLIP,FR BUMPER		10.00	4.00	23.00	30.80
M COVER,FR BUMPER		1.00	12.00	23.00	9.24
M FACE,FR BUMPER		1.00	703.00	23.00	541.31
M BODY KIT ATTRAGE		1.00	1643.00	00.00	1643.00
M DUCT,A/CLNR INTAKE		1.00	131.00	23.00	100.87

Estimate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Taufik 97495744

SURVEYOR SIGNATURE:

DATE: 19/10/20 @ 3pm

REMARKS: Not Authorize, Ex: Repairing before paint

taufik@lkkauto.com

08 days

Confirm & accepted by

16,993.56

Nett

16,883.45

7% GST on 16883.45

1181.84

Total Payable

18,065.29

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SMH8475P

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>LABOUR</u>					
1	REPLACE FRT END PANEL ASSY, REPAIR RHF CHASSIS MEMBER	1.00	550.00	0.00	550.00
2	SPARY PAINT RHF CHASSIS MEMBER	1.00	350.00	0.00	350.00
<u>PARTS</u>					
1	TANK, WINDSHIELD WASHER ✓ DE	1.00	74.00	23.00	56.98
2	MARK, THREE-DIA ✓ NEC	1.00	69.00	23.00	53.13
Total					1,010.11 110.11
7 % GST					70.71 7.71
Grand Total					1,080.82 117.82

Thank You.

Yours faithfully,

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554