

COMFORTDELGRO ENGINEERING PTE LTD

P1/2

REPAIR ESTIMATE

DATE: 19.10.2020

3P INSURANCE: AIG ASIA

MODEL: HYUNDAI I40

SURVEYOR: NA

VEH NO.: SHD3044M

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid / <i>DN</i>	1		\$2,174.90 /
	Bootlid Hinge (LH/RH) X <i>NM</i>	2	\$142.30	284.60
	Bootlid Lock Upper / <i>BT</i>	1		\$114.90 /
	Bootlid Lock Lower X <i>NM</i>	1		\$31.70
	Bootlid Hyundai Plate / <i>MC</i>	1		\$21.10 /
	Bootlid 'H' Emblem / <i>MC</i>	1		\$28.70 /
	Bootlid CRDI Plate / <i>MC</i>	1		\$27.90 /
	Bootlid I40 Emblem / <i>MC</i>	1		\$27.90 /
	Bootlid Lamp (LH/RH) (<i>CLH</i>) X <i>NM</i> (<i>CRH</i>) X <i>NM</i>	2	\$565.60	\$1,131.20
	Bootlid Moulding ? X <i>NM</i>	1		\$85.00
	Bootlid Lower Outer Garnish ? X <i>NM</i>	1		\$227.90
	Rear Bumper / <i>DN</i>	1		\$1,106.00 /
	Rear Bumper Reinforcement / <i>OR</i>	1		\$428.40 /
	Rear Bumper Stay (LH/RH) ? X <i>NM</i>	2	\$80.30	\$160.60
	Rear Bumper Clip (10 pcs) / <i>MC</i>	10	\$2.20	\$22.00 /
	Rear Bumper Side Bracket (LH/RH) / <i>OR</i>	2	\$35.60	\$71.20 /
	Rear Bumper Sponge / <i>OR</i>	1		\$119.50 /
	Rear Bumper Under Cover / <i>CUT</i>	1		\$228.00 /
	Rear Bumper Reflector (LH/RH) (<i>CLH</i>) - <i>OR</i> (<i>CRH</i>) X <i>NM</i>	2	\$32.00	\$64.00 <i>32</i>
	Tail Lamp (LH/RH) (<i>CLH</i>) / <i>OR</i> (<i>CRH</i>) X <i>NM</i>	2	\$697.80	\$1,395.60 <i>697.80</i>
	Exhaust Muffler (LH/RH) X <i>NM</i>	2	\$967.70	\$1,935.40
	Exhaust Pipe Centre X <i>NM</i>	1		\$730.10
	Rear Panel / <i>DN</i>	1		\$526.70 /
	Rear Panel Garnish / <i>OR</i>	1		\$57.70 /
	Rear Panel Lower Panel / <i>DN</i>	1		\$495.50 /
SPARE PARTS SUB TOTAL				\$11,496.50
LESS 20%				\$2,299.30
DISCOUNTED SPARE PARTS TOTAL				\$9,197.20

6180.20
- 297,
4944.16

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
			SHA3044M	P2/2
				Lim Tien Siong
	Bootlid ComfortDelGro ✓ <i>AL</i>	1		\$30.00
	Bootlid 65521111 ✓ <i>M</i>	1		\$30.00
	Reverse Sensor ✓ <i>AR</i>	1		\$135.70
	S/NETT TOTAL			\$195.70
	SPARE PARTS & OTHERS TOTAL			\$9,392.90
	Panel Beating		1120	\$1,200.00
	Spray Painting Charge		800	\$1,000.00
	Wiring Charge		30	\$40.00
	Tuff Kote		30	\$100.00
	Remove/Refix Reverse Sensor		30	\$120.00
	Remove/Refix Exhaust Pipe		? X	\$120.00
	Towing Fee – King Dolly			\$150.00 ✓
	LABOUR TOTAL			\$2,730.00
	ESTIMATE TOTAL			\$12,122.90

195.70

2160

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Stew (CLKK) WL AL

19/10/20, 3.30 pm

L/S

Ry AL SH

4 dgs

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: