



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15712/LEONG MUN EE, GENEVIEVE Reg No/Reg Date SMT7593A / 16/07/202 Date In/Mileage 19/10/2020/ 0 Chassis No MMBSTA13AKH003596 Engine No 3A92UJC2069 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 13:08	QUK	282 / Kevin Leong	58607
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPL FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA TO REPAIR ON FRT RH CHASSIS		452			1350 3150.00
E PNT98000 PAINT WORK FRT BUMPER, BONNET, SUPPORT, FRT RH DOOR, FRT RH CHASSIS & BOTH FRT FENDER		350			1750 2450.00
E PNT88000 TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR					? 120.00
M SUNDRY TO TOP UP AIRCON GAS					? 80.00
A 11900199 TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR					? 450.00
M SUNDRY PERFORM RUST PREVENTION					? 80.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA					X 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					✓ 120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA					8 ✓ 400.00
M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME					cut ✓ 50.00
M SUNDRY SUNDRIES					20. 50.00
M HEADLAMP ASSY, LH		1.00	660.00	23.00	X 508.20
M HEADLAMP ASSY, RH		1.00	660.00	23.00	one ✓ 508.20
M LAMP ASSY, FOG, FR LH		1.00	303.00	23.00	cut ✓ 233.31
M FACE, FR BUMPER		1.00	703.00	23.00	de ✓ 541.31
M COVER, HEADLAMP SUPT PANEL		1.00	62.00	23.00	arg ✓ 47.74
M AIR DAM, SIDE, FR RH		1.00	18.00	23.00	? 13.86

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour which may be required after repair work has commenced. Occasionally some items may be required
 after work has started and needed for repairs or replacement. However, the above estimate is based on our initial inspection and does not include
 deposit of 50% of the above estimate.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15712/LEONG MUN EE, GENEVIEVE Reg No/Reg Date SMT7593A / 16/07/202 Date In/Mileage 19/10/2020/ 0 Chassis No MMBSTA13AKH003596 Engine No 3A92UJC2069 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 13:08	QUK	282 / Kevin Leong	58607
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M AIR DAM, SIDE, FR LH		1.00	18.00	23.00	13.86
M GARNISH, FR BUMPER, RH		1.00	127.00	23.00	97.79
M GRILLE, FR UNDER		1.00	165.00	23.00	127.05
M BRACKET, FR BUMPER, LH		1.00	13.00	23.00	10.01
M BRACKET, FR BUMPER, RH		1.00	13.00	23.00	10.01
M GRILLE, RADIATOR		1.00	554.00	23.00	426.58
M HOOD		1.00	734.00	23.00	565.18
M HINGE, HOOD, LH } plus for		1.00	56.00	23.00	43.12
M HINGE, HOOD, RH }		1.00	56.00	23.00	43.12
M LATCH, HOOD		1.00	69.00	23.00	53.13
M FENDER, FR LH		1.00	497.00	23.00	382.69
M FENDER, FR RH		1.00	497.00	23.00	382.69
M PANEL, HEADLAMP SUPPORT, UPR		1.00	65.00	23.00	50.05
M PANEL ASSY, FR END		1.00	1055.00	23.00	812.35
M SHIELD, FR WHEELHOUSE, RH		1.00	98.00	23.00	75.46

Estimate

SURVEYOR NAME: Tanphin 97475749SURVEYOR SIGNATURE: TanphinDATE: 19/10/20 Not AuthorisedREMARKS: Ex: to be advise, ResurveyResurvey before paint, tanphin@lkkauto.com
26 daysLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

Acknowledged by Repairer

7% GST on

Nett	12,005.71	12,005.71
	840.40	
Total Payable		12,846.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of damage to the windscreen or other repair requiring the replacement of the windscreen.