

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO/GST Reg. No. 201019626G

SHC5225A

AAD20010-066

*Not Authorized**Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

16 OCT 2020

SHC5225A

JTDKB3FU303091228

TOYOTA

PRIUS G4

15/10/2020

AIG

3/8/2020

- | | PART |
|---|---|
| 1 | PANEL SUB-ASSY, FRONT DOOR, RH |
| 1 | MOTOR ASSY, POWER WINDOW REGULATOR, RH |
| 1 | REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH |
| 1 | TAPE, BLACK OUT, NO.1 FRT RH |
| 1 | TAPE, BLACK OUT, NO.2 FRT RH |
| 1 | TAPE, BLACK OUT, NO.3 FRT RH |
| 1 | PANEL SUB-ASSY, REAR DOOR, RH |
| 1 | TAPE, BLACK OUT, NO.1 REAR RH |
| 1 | TAPE, BLACK OUT, NO.2 REAR RH |
| 1 | TAPE, BLACK OUT, NO.3 REAR RH |
| 1 | HINGE ASSY, REAR DOOR, LOWER RH |
| 1 | REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH |
| 1 | MOULDING ASSY, BODY ROCKER PANEL, RH |
| 1 | REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH |
| 1 | PANEL SUB-ASSY, QUARTER, RH |

LIST		
\$	<i>R</i> 1,300.70	X
\$	<i>Rh</i> 926.00	X
\$	<i>R</i> 238.30	X
\$	<i>nn</i> 13.30	X
\$	<i>nn</i> 43.50	X
\$	<i>nn</i> 26.30	X
\$	<i>Bl/wap</i> 1,294.90	✓
\$	<i>Rh</i> 21.90	—
\$	<i>Rh</i> 34.90	—
\$	<i>Rh</i> 15.40	✓
\$	<i>R</i> 87.10	X
\$	<i>Rh</i> 206.70	X
\$	<i>R</i> 594.80	X
\$	<i>R</i> 343.40	X
\$	<i>Rh</i> 871.50	✓
TOTAL	\$ 6,018.70	
25%	\$ 1,504.68	
	\$ 4,514.03	

Special Nett

- | | |
|------|--------------------------------|
| 1 | FRONT DOOR STICKER 'TRANS-CAB' |
| 1 | REAR DOOR STICKER "6555-3333" |
| 1 | REAR FENDER LINER CLIP |
| 1 | REAR BUMPER CLIP |
| 1SET | ROCKER PANEL MOULDING CLIP |

\$	<i>Rh</i> 100.00	<i>Gain</i>
\$	<i>Rh</i> 100.00	<i>Gain</i>
\$	<i>nn</i> 75.00	X
\$	<i>nn</i> 85.00	X
\$	<i>nn</i> 65.00	X
TOTAL	\$ 425.00	

TOTAL PARTS \$ 4,939.03

AAD20010-066

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6257 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5225A

LABOUR

To transfer of door fittings, attachment and perform water seepage test.	\$	300.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	801
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
Putty And Spray Painting Of The Affected Portion.	\$	1,400.00	801
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 4,120.00

Over All Total \$ 9,059.03

(PART-BY-PART) Repair Days

20 days

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: