AAD2010-043

15 OCT 2020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

fittings and other, to enable repair.

CO./GST Reg. No. 201019626G

SHD9651X

SHD9651X Vehicle No.: JTDKB3FU103081572 Chassis No.: TOYOTA Vehicle Make: **PRIUS** Vehicle Model: 9/10/2020 Date of Accident: FIRST CAPITAL Third Party Insurer: 27/6/2019 Date of Registration: LIST PART n 977.80 🗶 FENDER SUB-ASSY, FRONT RH 206.70 🗶 Sm \$ LINER, FRONT FENDER, RH 54.60 🗶 EMBLEM, SIDE PANEL √ 1,436.60 X MIRROR ASSY, OUTER REAR VIEW, RH N 1,300.70 X PANEL SUB-ASSY, FRONT DOOR, RH Na 13.30 X TAPE, BLACK OUT, NO.1 FRT RH NA 43.50 L TAPE, BLACK OUT, NO.2 FRT RH NA 26.30 X TAPE, BLACK OUT, NO.3 FRT RH 4,059.50 TOTAL \$ 1,014.88 25% 3,044.63 **Special Nett** 100.00 bosa 1 FRONT DOOR STICKER "TRANSCAB" 6555 3333 \$ 65.00 🗶 \$ 1SET CLIP, FRONT FENDER LINER 60.00 X \$ 1SET CLIP, FRONT DOOR WEATHERSTRIP 165.00 TOTAL \$ 3,209.63 TOTAL PARTS \$ LABOUR To remove and refit interior fittings, trimings, garnish,

NN 380.00 X

\$

Trans-cab Auto Services Pte Ltd

AAD2010-043

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9651X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, 1,400.00 1501 Adjust And Realign The Same NN 170.00 X To transfer of tire, rim and on wheel balancing. 1,400.00 4401 Putty And Spray Painting Of The Affected Portion. To Rust-Proofing and apply undercoat Of The Affected 240.00 Areas. ~~ 170.00 X To Check Electrical Lighting Concerned. 3,760.00 TOTAL \$ 6.969.63 Over All Total \$

(PART-BY-PART) Repair Days

15 days

For Official Use

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting Prepared By: To display damaged part(s) during resurvey (Accident Dept) Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Verify By cknowledged by Repairer (Accident Workshop) ignature: ate: Checked By (Finance Dept)