

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM20011319/Esf3s2 AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 28-10-2020 ATTN: PETER WANG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. PA 6540Z Veh. Inspected SKD 4573K Policy No. Coverage (\$) 0.00 S0M02VLT 0.00 Claim No. Excess (\$) PETER WANG 20/10/2020 **Assign From Assign Date** 2. **Vehicle Particulars & Condition** Make & Model MERCEDES BENZ C 180 1597 c.c 2011 Engine No. HIDDEN Year of Reg. WDD2040452A629786 Chassis No. Colour **SILVER** Odometer 147094 KM Steering IN ORDER **Brakes** IN ORDER Modification SPORTS RIM **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 5 mm 215/50 R16 **MICHELIN** R/H Front Tyre L/H Front Tyre 215/50 R16 **MICHELIN** 5 mm 215/50 R16 **MICHELIN** 5 mm R/H Rear Tyre 215/50 R16 **MICHELIN** 5 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTTION. 5. **General Information** 16/10/2020 Inspect Date / Time 20/10/2020 (09:20 AM) **Accident Date** PRECISE AUTO SERVICE Survey held at NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000 5b. **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM20011319/Esf3s2

Inspected By

1

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.