

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

16/10/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG.

Jasper.

Accident date: 15-10-2020

Estimated repair cost for vehicle no: SKE4321R HYUNDAI ELANTRA 1.6 A '12

CHASSIS: KMHDH41CMCU421170

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid Distorted		\$1,188.70 ✓
2	2	Rear Boot Lid Hinge Best	\$84.00	\$168.00 ✓
3	1	Rear Boot Lid Emblem Logo		\$38.00 ✓
4	1	Rear Boot Lid Elantra Logo		\$40.00 ✓
5	1	Rear Boot Lid ELITE Logo		\$41.90 ✓
6	2	Rear Boot Lid Side Reflector LH cmltd	\$298.50	\$597.00 298.50
7	1	Rear Boot Lid Number Plate cut		\$50.00 ✓
8	1	Rear Boot Lid Inner Lock Jam'd		\$125.00 ✓
9	1	Rear Boot Lid Weatherstrip cut		\$115.80 ✓
10	1	Rear Boot Lid Inner Trim Board cmltd		\$285.00 ✓
11	8	Rear Boot Lid Inner Trim Board Clip new	\$6.50	\$52.00 30 ✓
12	1	Rear Boot Lid Reverse Camera (Special Nett) new		\$680.00 +
13	1	Rear Windscreen Seal xbl new		\$105.00 X
14	2	Rear Tail Lamp LH cmltd, RH cut	\$354.80	\$709.60 ✓
15	4	Rear Tail Lamp Clip new	\$8.00	\$32.00 145
16	2	Rear Tail Lamp Panel LH Bulbs	\$556.20	\$1,112.40 556.20
17	1	Rear Bumper Distorted		\$454.80 ✓
18	8	Rear Bumper Clip new	\$6.50	\$52.00 30
19	2	Rear Bumper Side Retainer new	\$38.00	\$76.00 ✓
20	2	Rear Bumper Side Reflector LH cmltd	\$58.00	\$116.00 58
21	1	Rear Bumper Lower new		\$282.00 +
22	1	Rear Bumper Inner Foam new		\$162.80 +
23	1	Rear Bumper Reinforcement cmltd		\$328.00 ✓
24	2	Rear Bumper Reinforcement Bracket Best.	\$94.60	\$189.20 ✓
25	5	Rear Bumper Reinforcement Top & Lower Bracket	\$19.80	\$99.00 ✓
26	1	Rear Bumper Reinforcement Antenna Sensor cmltd		\$285.40 ✓
27	1	Rear Bumper Reverse Sensor (Special Nett) Jam'd		\$350.00 200/500

28	1	Rear End Panel	Distorted		\$593.80	—
29	1	Rear End Panel Top Garnish	Delam d		\$105.00	—
30	1	Rear L/H Fender	Repair		\$1,560.80	+
31	1	Rear L/H Fender Cowling	torn		\$58.50	4
32	8	Rear L/H Fender Cowling Clip	new	\$6.50	\$52.00	20.
33	2	Rear Fender Inner Trim Board	LH torn	\$267.50	\$535.00	267.50
34	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	30.
35	1	Rear Spare Tyre Panel	Repair		\$486.00	X.
36	1	Rear Spare Tyre Panel Top Cover	Delam d		\$255.00	—
37	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00	X 250 (SN)

6117.70 S.N: 450
4894.16

Subtotal :- \$11,935.70

Labour charges

To remove & refit cushion & trim board	\$280.00	80.
To remove & refit reverse camera	\$180.00	50
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear windscreen	\$120.00	X
Gum	\$50.00	X
To check wiring	\$100.00	30
Towing fee	\$150.00	X
Tuff kote	\$150.00	100.
Panel beating	\$2,200.00	1200.
Spray painting	\$2,000.00	1200.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$5,330.00

Total:- \$17,265.70

To transfer boothid
fittings

150 80

total 8134.16
L/S: 6.5K

Adrian Lj
H/S 16/10/20
09 Days

6.5K

09 Days