

# Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921  
 Email: ryderautoworkshop@gmail.com  
 Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# SKC290H  
 Accident Date 18/10/2020

Model: TOYOTA VIOS  
 (15/7/2011)

Location PIE TOWARDS JALAN BAHAR EXIT

3P: 5L33696J (AIG)


S/Nos.	QTY	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper / DR	-	-	-
2	10 pcs	Rear bumper clips / MC	-	30.00	-
3	2 pcs	Rear bumper o/s & n/s retainer / DR	-	-	-
4	2 pcs	Rear bumper o/s & n/s reflector (LN) - DR	-	-	-
5	1 pc	Rear boot cover / DD	-	-	-
6	1 pc	Rear boot cover weatherstrip / CRU	-	-	-
7	1 pc	Rear boot cover emblem / MC	-	-	-
8	1 pc	Rear boot cover Vios emblem / MC	-	-	-
9	1 pc	Rear boot cover E emblem / MC (T)	-	-	-
10	1 pc	Rear boot cover lock (Upper) / IT	-	-	-
11	1 pc	Rear boot cover lock (Lower) X	-	-	-
12	2 pcs	Rear boot cover o/s & n/s hinges / IT	-	-	-
13	2 pcs	Rear boot cover o/s & n/s rubber stopper X	-	-	-
14	1 pc	Rear boot cover moulding ?	-	-	-
15	4 pcs	Rear boot cover moulding clips ?	-	-	-
16	1 pc	Rear end panel / DD	-	-	-
17	1 pc	Rear end panel inner trim ?	-	-	-
18	4 pcs	Rear tail-lamp panel inner trim clips ?	-	-	-
19	2 pcs	Rear o/s & n/s tail-lamp / DR	-	-	-
20	4 pcs	Rear o/s & n/s tail-lamp clips X	-	16.00	-
21	1 pc	Rear n/s tail-lamp panel / BT	-	-	-
22	1 pc	Rear spare wheel board cover ?	-	-	-
23	1 pc	Rear boot floor panel ?	-	-	-
24	2 pcs	Rear boot floor o/s & n/s sponge ?	-	-	-
25	1 pc	Rear boot floor sponge (Rear) ?	-	-	-
26	1 pc	Rear n/s fender / DD	-	-	-
27	1 set	Rear windscreen moulding / MC	-	-	-
28	1 pc	Rear windscreen sealant / MC	-	-	-
29	1 set	Rear reverse sensor / DR	-	280.00	-
Sub-Total:			0.00	326.00	0.00
			25%	0%	0%
After Less %:			0.00	326.00	0.00

Labour			
1	To dismantle rear portion damaged parts, straighten & welding.	1,400.00	1200
2	To spray painting.	1,300.00	1000
3	To re-align rear chassis frame.	300.00	200
4	To remove & replace rear reverse sensor.	50.00	30
5	To remove and refit rear windscreen	140.00	120
6	To check wiring.	30.00	-
7	To re-seal anti-rust.	100.00	30
Sub-Total:		3,320.00	
Total:		3,646.00	
After Less 20%:		2,916.80	

Chan San Choon  
 Director  
 DipEng, AAE MIMI, MSAE (Aust)

SKVE (LKK) wtl Pnl  
 LIS  
 20/10/20, 10-30 am  
 Ry AL Sp

14 days



AL 8778 1999  
 24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: