

ESTIMATE OF REPAIR

Veh# SKC290H

Model: TOYOTA VIOS

Accident Date 18/10/2020

(15/7/2011)

Location PIE TOWARDS JALAN BAHAR EXIT

3P: SLU3696U (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	560.00		
2	10 pcs	Rear bumper clips		30.00	
3	2 pcs	Rear bumper o/s & n/s retainer	80.00		
4	1 pc	Rear bumper o/s & n/s reflector	90.00		
5	1 pc	Rear boot cover	948.12		
6	1 pc	Rear boot cover weatherstrip	160.00		
7	1 pc	Rear boot cover emblem	70.00		
8	1 pc	Rear boot cover Vios emblem	68.00		
9	1 pc	Rear boot cover E emblem	66.00		
10	1 pc	Rear boot cover lock (Upper)	280.00		
11	1 pc	Rear boot cover lock (Lower)	100.00		
12	2 pcs	Rear boot cover o/s & n/s hinges	100.00		
13	2 pcs	Rear boot cover o/s & n/s rubber stopper	40.00		
14	1 pc	Rear boot cover moulding	120.00		
15	4 pcs	Rear boot cover moulding clips		16.00	
16	1 pc	Rear end panel	946.92		
17	1 pc	Rear end panel inner trim	220.00		
18	4 pcs	Rear tail-lamp panel inner trim clips		16.00	
19	2 pcs	Rear o/s & n/s tail-lamp	760.00		
20	4 pcs	Rear o/s & n/s tail-lamp clips		20.00	
21	1 pc	Rear n/s tail-lamp panel	276.12		
22	1 pc	Rear spare wheel board cover	260.00		
23	1 pc	Rear boot floor panel	1,053.72		
24	2 pcs	Rear boot floor o/s & n/s sponge	76.00		
25	1 pc	Rear boot floor sponge (Rear)	60.00		
26	1 pc	Rear n/s fender	1,175.04		
27	1 set	Rear windscreen moulding		120.00	
28	1 pc	Rear windscreen sealant		80.00	
29	1 set	Rear reverse sensor		280.00	
		Sub-Total:	7,509.92	562.00	0.00
				25%	0% 0%
		After Less %:	5,632.44	562.00	0.00

✓ BR \$419
 ✓ NEC
 ✓ BR
 ✓ BR (LH only)
 ✓ DD \$566
 ✓ CRU
 ✓ NEC
 ✓ NEC
 ✓ NEC
 ✓ BT \$185
 X NN
 ✓ BT
 X NN
 X NN - Repeated item 6
 X NN
 ✓ DD \$539
 ✓ CRU \$165
 ✓ NEC \$10 Nett
 ✓ BR \$690.20
 X NN
 ✓ DD \$199
 ✓ TN
 ✓ DD \$781.65
 ✓ BR (LH only)
 X NN
 ✓ DD
 ✓ NEC
 ✓ NEC \$40
 ✓ BR \$200 Nett
 5429.89
 -25%
 4072.41
 Nett - 400

Labour			
1	To dismantle rear portion damaged parts, straighten & welding.	1,200.00	1100 ✓
2	To spray painting.	1,000.00	✓
3	To re-align rear chassis frame.	200.00	100 ✓
4	To remove & replace rear reverse sensor.	30.00	✓
5	To remove and refit rear windscreen	120.00	✓
6	To check wiring.	30.00	✓
7	To re-seal anti-rust.	30.00	✓
	Sub-Total:	2,610.00	2410
	Total:	8,804.44	
	After Less 20%:	7,043.55	


 Chan San Choon
 Director
 DipEng, AAE MIMI,MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Steve (LKK)
 20/10/20
 Without Prejudice
 L/S
 Resurvey After Spray
 12 repair days

P - 4072.41
 N - 400
 L - 2410
 = 6882.41
 L/S - 5505.92
 = 5500



Acknowledged by Repairer
 Signed by
SAFE
 24 hr accident call
 8778 1999

