

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Not Notified
6/1/20
Runny After Paint
26/10/20 4.05pm
2 days

Date : 19.10.2020
Vehicle No : SLP2579H
Veh Make/Model : Honda Accord V6 3.5L
YOM : 2008
Chassis No : MRHCP36308P040043
Date of Accident : 17.10.2020

No	Qty	Description	Amount \$
		List Items:-	
1	1	Rear Bumper	\$ <i>Bu</i> 709.10
2	2	Rear Bumper Side Retainer	\$ <i>Di</i> 35.00
3	2	Rear Lamp Lower Bracket LH & RH	\$ <i>Di</i> 16.00
4	2	Rear Lamp LH & RH	\$ <i>n</i> 591.60
5	1	Rear End Panel	\$ <i>n</i> 287.80
6	1	Rear End Panel Garnish	\$ <i>bu</i> 97.70
7	1	Rear Reinforcemt Bar	\$ <i>Di</i> 145.60
8			
9			
10			
11			
12			
13			
14			
15			
16		LKK Auto Consultants hence notify the Repairer of the following:	
17		• To resurvey before/after spray painting	
18		• To display damaged part(s) during resurvey	
19		• Parts prices are subject to confirmation	
20		• Third party survey is on a "without prejudice" basis	
21		• No illegal modification(s) is allowed	
22		• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
23		Acknowledged by Repairer	
24		Signature:	
25		Date:	
26			
27			
28			
29			
30			
Total - List Item			\$ 1,882.80
Less 20%			\$ 376.56
Total			\$ 1,506.24

10 Ang Mo Kio Industrial Park 2A

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Date : 19.10.2020
Vehicle No : SLP2579H
Veh Make/Model : Honda Accord V6 3.5L
YOM : 2008
Chassis No : MRHCP36308P040043
Date of Accident : 17.10.2020

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

✓
✓
x

$$\begin{array}{r} 2206 \\ 2001 \\ \times \\ 156 \\ \hline 601 \\ 11030 \\ 44120 \\ \hline 344916 \end{array}$$