

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKM6010H [YOUR INSURED] & GBD7304H [OUR CLIENT]
ON 19/10/2020.

ESTIMATED REPAIR COSTS FOR GBD7304H

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	REAR TAILGATE <i>Yes</i>	\$ 1,679.06	X
4PC	REAR TAILGATE HINGE @ \$102.71 EACH <i>0/S St 2pc N/S H</i>	\$ 410.84	LL205
1PC	REAR TAILGATE LOCK RH <i>St</i>	\$ 217.31	L
1PC	REAR TAILGATE LOCK BRACKET RH <i>MS</i>	\$ 97.20	X
1PC	REAR TAILGATE STOPPER RH <i>Svc</i>	\$ 51.78	X
1PC	REAR TAILGATE STOPPER BRACKET RH <i>St</i>	\$ 96.27	L
1PC	REAR SIDE GATE RH <i>MS</i>	\$ 1,854.72	X
1PC	TAIL LAMP RH <i>broken</i>	\$ 393.70	L
1PC	TAIL LAMP PANEL RH <i>St</i>	\$ 89.96	L
1PC	TAIL LAMP REFLECTOR RH <i>broken</i>	\$ 284.50	L
1PC	REAR FLOOR PANEL <i>MS</i>	\$ 2,880.90	X
2PC	CHASSIS BRACKET <i>MS</i>	\$ 314.52	X
1PC	REAR END PANEL <i>2entel</i> <i>584.30</i>	\$ 843.20	L
1PC	REAR EXHAUST PIPE <i>St</i> <i>570.70</i>	\$ 1,489.92	L
1PC	REAR EXHAUST MOUNTING <i>MS</i>	\$ 194.56	X
1PC	REAR NO. PLATE LAMP <i>MS</i>	\$ 169.00	X
2442.16		PARTS SUM: \$ 11,067.44	
1831.62		PARTS LESS 25%: \$ 2,766.86	
		PARTS TOTAL: \$ 8,300.58	

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE <i>broken</i>	\$ 40.00	20/-
*	TO SUPPLY FLOOR PANEL SEALANT <i>MS</i>	\$ 80.00	X
*	TO SUPPLY REAR STEP BAR <i>MS</i>	\$ 300.00	X
*	TO SUPPLY 70KM STICKER <i>MS</i>	\$ 30.00	15/-
*	TO SUPPLY DYNA STICKER <i>MS</i>	\$ 400.00	20/-
*	TO SUPPLY 13 PAX STICKER <i>MS</i>	\$ 30.00	20/-
*	TO SUPPLY '1500KG' STICKER <i>MS MS</i>	\$ 100.00	20/- X
*	TO SUPPLY 'NAGANO TOYOTA' STICKER <i>MS MS</i>	\$ 200.00	20/- X

*	TO SUPPLY CAUTION SIGN STICKER H-H	\$ 100.00 X
*	TO RNR REAR METAL DECK TO FACILITATE REPAIRS H-H	\$ 1,800.00 X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,600.00 450/-
*	TO TUFF COAT DAMAGED AREAS 1150/-	\$ 300.00 40/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00 60/-

LABOUR & S/N TOTAL: \$ 7,230.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 15,530.58

20/10/22 e 1800hrs

N/A Antenna

2 Pairs

4 days.

1 year

2 Kk Antenna

8

3056.62

2/s 2400/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: