

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKM6010H [YOUR INSURED] & GBD7304H [OUR CLIENT]
ON 19/10/2020.

ESTIMATED REPAIR COSTS FOR GBD7304H

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	REAR TAILGATE <i>199</i>	\$ 1,679.06
4PC	REAR TAILGATE HINGE @ \$102.71 EACH <i>0/S 3+ 2pc N/S H</i>	\$ 410.84
1PC	REAR TAILGATE LOCK RH <i>1st</i>	\$ 217.31
1PC	REAR TAILGATE LOCK BRACKET RH <i>MS</i>	\$ 97.20
1PC	REAR TAILGATE STOPPER RH <i>SVC</i>	\$ 51.78
1PC	REAR TAILGATE STOPPER BRACKET RH <i>1st</i>	\$ 96.27
1PC	REAR SIDE GATE RH <i>MS</i>	\$ 1,854.72
1PC	TAIL LAMP RH <i>broken</i>	\$ 393.70
1PC	TAIL LAMP PANEL RH <i>1st</i>	\$ 89.96
1PC	TAIL LAMP REFLECTOR RH <i>broken</i>	\$ 284.50
1PC	REAR FLOOR PANEL <i>MS</i>	\$ 2,880.90
2PC	CHASSIS BRACKET <i>MS</i>	\$ 314.52
1PC	REAR END PANEL <i>2nd</i>	\$ 843.20
1PC	REAR EXHAUST PIPE <i>1st</i>	\$ 1,489.92
1PC	REAR EXHAUST MOUNTING <i>MS</i>	\$ 194.56
1PC	REAR NO. PLATE LAMP <i>MS</i>	\$ 169.00

PARTS SUM: \$ 11,067.44

PARTS LESS 25%: \$ 2,766.86

PARTS TOTAL: \$ 8,300.58

2442.16
1831.62

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE <i>broken</i>	\$ 40.00 <i>20/-</i>
*	TO SUPPLY FLOOR PANEL SEALANT <i>MS</i>	\$ 80.00 <i>X</i>
*	TO SUPPLY REAR STEP BAR <i>MS</i>	\$ 300.00 <i>X</i>
*	TO SUPPLY 70KM STICKER <i>MS</i>	\$ 30.00 <i>15/-</i>
*	TO SUPPLY DYNA STICKER <i>MS</i>	\$ 400.00 <i>20/-</i>
*	TO SUPPLY 13 PAX STICKER <i>MS</i>	\$ 30.00 <i>20/-</i>
*	TO SUPPLY '1500KG' STICKER <i>MS MS</i>	\$ 100.00 <i>20/- X</i>
*	TO SUPPLY 'NAGANO TOYOTA' STICKER <i>MS MS</i>	\$ 200.00 <i>20/- X</i>

75/-

	TO SUPPLY CAUTION SIGN STICKER 44	\$ 100.00	X
*	TO RNR REAR METAL DECK TO FACILITATE REPAIRS 44	\$ 1,800.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,600.00	450/-
*	TO TUFF COAT DAMAGED AREAS 1150/-	\$ 300.00	40/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	60/-

LABOUR & S/N TOTAL: \$ 7,230.00


GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 15,530.58

20/10/22 @ 1800hrs
N/A Andrew

2 hrs 4 days.

1 year

2kk Auto



3056.62
L/S 2400/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: