

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBF4764Y

No.	Qty	List Items	
1	1	Front bumper	\$ R 452.10 X
2	1	Front bumper LH side retainer	\$ In 191.30 X
3	1	Front bumper inner reinforcement	\$ R 364.40 X
4	1 set	Front bumper clips	\$ Nn 40.00 X
5	1	LH headlamp	\$ CM 748.10 —
6	1	Front LH corner panel	Br/Bn 258.10 —
7	1	Front grille assy	\$ In 580.80 X
8	1	Front bonnet	\$ R 756.60 X
9	1	Front bonnet centre "TOYOTA" logo	\$ Nn 66.10 ✓
			\$ 3,457.50
Less 25%			\$ 864.38
Total :			\$ 2,593.13

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 700.00 350
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 600
3	To check wirings & lightings.	\$ 40.00 20
4	To remove, refit A/c condenser, radiator and etc..	\$ Nn 150.00 X
5	To supply and apply anti rust treatment	\$ Nn 80.00 X
Total :		\$ 1,970.00

Total Parts and Labour : \$ 4,563.13

Not Withheld
Presumy B4 painting
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: